

SERVICE REPORT

Australian Unity - Geelong Grove Community Centre

**50 Barwarre Road
 Marshall
 Victoria 3216**

**Report Number R-01593
 Reference GEELONG-2400796**

Service Date:

Scope of Works

Path of Travel & Discharge to Exit (2012): Quarterly (17)

0	Critical Defects	A defect that renders a system inoperative.
1	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.
17	Passed Assets	

Servicing Summary

Service	Asset	Quantity
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	17

Maintenance

Path of Travel & Discharge to Exit (2012): Quarterly

Asset	Status
017 - Path of Travel & Discharge to Exit Discharge from Exit Community Centre	PASS

Asset		Status
		
016 - Path of Travel & Discharge to Exit Discharge from Exit	Community Centre	PASS
		
015 - Path of Travel & Discharge to Exit Discharge from Exit	Community Centre	PASS
		
014 - Path of Travel & Discharge to Exit Exit Door	Community Centre	PASS
		
013 - Path of Travel & Discharge to Exit Discharge from Exit	Community Centre	PASS
		
012 - Path of Travel & Discharge to Exit Exit Door	Community Centre	PASS
		
011 - Path of Travel & Discharge to Exit Discharge from Exit	Community Centre	PASS
		

Asset		Status
010 - Path of Travel & Discharge to Exit Exit Door	Community Centre	PASS
		
009 - Path of Travel & Discharge to Exit Discharge from Exit	Community Centre	PASS
		
008 - Path of Travel & Discharge to Exit Automatic Doors	Community Centre	PASS
		
007 - Path of Travel & Discharge to Exit Exit Door	Community Centre, cottage	PASS
		
006 - Path of Travel & Discharge to Exit Discharge from Exit	Workshop	PASS
		
005 - Path of Travel & Discharge to Exit Exit Door	Workshop	PASS
		
004 - Path of Travel & Discharge to Exit Discharge from Exit	Men's Shed	PASS

Asset	Status
-------	--------



003 - Path of Travel & Discharge to Exit Exit Door

Men's Shed

PASS



002 - Path of Travel & Discharge to Exit Discharge from Exit

Cottage

PASS



001 - Path of Travel & Discharge to Exit Exit Door

Cottage

PASS



Repairs

017 - Path of Travel & Discharge to Exit Discharge from Exit
Community Centre

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 14th Aug 2024 9:53AM

ID: 1324 [↗](#)


Last Verified: 14th Aug 2024 9:57AM

Description:

Door catching on top and bottom of the frame

Location:

Community Center



Click photos to enlarge

Parts/Labour

Quantity

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician

Date/Time

Accreditations

Signature

Micra Service
Technician

None

Mike Alford

None

Company Accreditations: