

## SERVICE REPORT

<b>Styleknit</b>	<b>Report Number R-00231</b>
<b>Factory 10, 35 Dunlop Road</b>	<b>Reference</b>
<b>Mulgrave</b>	<b>Service Date:</b>
<b>Victoria 3170</b>	

<b>Scope of Works</b>
Path of Travel & Discharge to Exit (2012): Quarterly (0)

<b>0 Critical Defects</b>	A defect that renders a system inoperative.
<b>0 Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>0 Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0 Recommendations</b>	A modification suggested to improve the system performance.
<b>0 Informational Notes</b>	Detailed advice or general comment.

<b>Servicing Summary</b>		
<b>Service</b>	<b>Asset</b>	<b>Quantity</b>
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	1

## Maintenance

### Path of Travel & Discharge to Exit (2012): Quarterly

Asset		Status
001 - Path of Travel & Discharge to Exit Exit Door	Styleknit ground floor exit	<b>PASS</b>



[Click photos to enlarge](#)

### Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

#### Company Accreditations: