

## SERVICE REPORT

<b>Styleknit</b>	<b>Report Number R-00219</b>
<b>11/35 Dunlop Rd, Mulgrave VIC 3170, Australia</b>	<b>Reference</b>
	<b>Service Date: 19th April 2024</b>

### Scope of Works

09 - Fire Hose Reels (2012): Six-monthly (0)

<b>0 Critical Defects</b>	A defect that renders a system inoperative.
<b>2 Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>0 Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0 Recommendations</b>	A modification suggested to improve the system performance.
<b>0 Informational Notes</b>	Detailed advice or general comment.

### Servicing Summary

Service	Asset	Quantity
09 - Fire Hose Reels (2012): Six-monthly	09 - Fire Hose Reels	2

## Maintenance

### 09 - Fire Hose Reels (2012): Six-monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset	Status
007 - Hose Reel 36m - 19mm - Fire Affinity ground floor office	<b>FAIL</b>

Asset	Status
<b>Non-critical defect</b> ID: 855 <a href="#">↗</a>	Added: 19th Apr 2024 3:46PM Last Verified: 19th Apr 2024 3:47PM
<p><b>Description:</b> Hose reel is not accessible/obstructed</p> <p><b>Resolution:</b> Technician to investigate cause of issue and rectify where possible (excluding parts)</p>	
 <p>Click photos to enlarge</p>	

001 - Hose Reel 36m - 19mm - Fire

Micra Air Factory

**FAIL**

<b>Non-critical defect</b> ID: 850 <a href="#">↗</a>	Added: 19th Apr 2024 2:55PM Last Verified: 19th Apr 2024 2:55PM
<p><b>Description:</b> Hose reel is not installed</p> <p><b>Resolution:</b> Technician to investigate cause of issue and rectify where possible (excluding parts)</p>	
 <p>Click photos to enlarge</p>	

### Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Company Accreditations: