

SERVICE REPORT

<p>Styleknit</p> <p>Factory 10, 35 Dunlop Road Mulgrave Victoria 3170</p>	<p>Report Number R-00232</p> <p>Reference</p> <p>Service Date:</p>
---	---

Scope of Works
10 - Portable and Wheeled Fire Extinguishers (2012): Six-monthly (0)

0	Critical Defects	A defect that renders a system inoperative.
1	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
9	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
1	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.

Servicing Summary		
Service	Asset	Quantity
10 - Portable and Wheeled Fire Extinguishers (2012): Six-monthly	10 - Fire Extinguishers - Portable	5

Maintenance

10 - Portable and Wheeled Fire Extinguishers (2012): Six-monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset

Status

ex5 - Fire Extinguisher DCP AB(E)
4.5KG

Styleknit ground floor rear

FAIL



[Click photos to enlarge](#)

Non-conformance

ID: 869 [↗](#)

Added: 19th Apr 2024 4:40PM

Last Verified: 19th Apr 2024 4:43PM

Description:

5-yearly pressure test overdue

Resolution:



[Click photos to enlarge](#)

ex4 - Fire Extinguisher DCP AB(E)
4.5KG

Styleknit ground floor

FAIL

Non-conformance

ID: 868 [↗](#)

Added: 19th Apr 2024 4:33PM

Last Verified: 19th Apr 2024 4:37PM

Description:

5-yearly pressure test overdue

Resolution:



[Click photos to enlarge](#)

Non-conformance

ID: 867 [↗](#)

Added: 19th Apr 2024 4:36PM

Last Verified: 19th Apr 2024 4:37PM

Description:

Location sign is missing / visible

Resolution:



[Click photos to enlarge](#)

Asset

Status

Non-conformance

ID: 866 [↗](#)

Added: 19th Apr 2024 4:36PM

Last Verified: 19th Apr 2024 4:37PM

Description:

Support bracket is not securely attached to wall/suitable feature

Resolution:



[Click photos to enlarge](#)

**ex3 - Fire Extinguisher DCP AB(E)
9.0KG**

Styleknit ground floor

FAIL



[Click photos to enlarge](#)

Non-critical defect

ID: 864 [↗](#)

Added: 19th Apr 2024 4:28PM

Last Verified: 19th Apr 2024 4:29PM

Description:

Discharge nozzle holder missing

Resolution:



[Click photos to enlarge](#)

Non-conformance

ID: 865 [↗](#)

Added: 19th Apr 2024 4:27PM

Last Verified: 19th Apr 2024 4:29PM

Description:

5-yearly pressure test overdue

Resolution:



[Click photos to enlarge](#)

Non-conformance

ID: 863 [↗](#)

Added: 19th Apr 2024 4:29PM

Last Verified: 19th Apr 2024 4:29PM

Description:

Location sign too high

Resolution:



[Click photos to enlarge](#)

Asset

Status

**ex2 - Fire Extinguisher DCP AB(E)
2.0KG**

Styleknit ground floor

FAIL



Click photos to enlarge

Non-conformance

Added: 19th Apr 2024 4:22PM

ID: 862 [↗](#)

Last Verified: 19th Apr 2024 4:23PM

Description:

Location sign at incorrect height

Resolution:



Click photos to enlarge

Non-conformance

Added: 19th Apr 2024 4:20PM

ID: 861 [↗](#)

Last Verified: 19th Apr 2024 4:22PM

Description:

5-yearly pressure test overdue

Resolution:



Click photos to enlarge

Recommendation

Added: 19th Apr 2024 4:21PM

ID: 860 [↗](#)

Last Verified: 19th Apr 2024 4:22PM

Description:

Recommend a larger Abe 4.5 kg extinguishers

Resolution:



Click photos to enlarge

**Ex1 - Fire Extinguisher DCP AB(E)
2.0KG**

Styleknit 1st floor office

FAIL



Click photos to enlarge

Asset**Status****Non-conformance**ID: 856 [↗](#)

Added: 19th Apr 2024 4:04PM

Last Verified: 19th Apr 2024 4:04PM

Description:

5-yearly pressure test overdue

Resolution:

Click photos to enlarge

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Company Accreditations: