

SERVICE REPORT

Styleknit	Report Number R-01053
Factory 10, 35 Dunlop Road	Reference
Mulgrave	Service Date: 3rd October 2024
Victoria 3170	

Scope of Works
09 - Fire Hose Reels (2012): Annual (1)
09 - Fire Hose Reels (2012): Annual Flow Test (0)

0	Critical Defects	A defect that renders a system inoperative.
1	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.
1	Passed Assets	

Servicing Summary		
Service	Asset	Quantity
09 - Fire Hose Reels (2012): Annual	09 - Fire Hose Reels	1

Maintenance

09 - Fire Hose Reels (2012): Annual

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset

Status

007 - Hose Reel 36m - 19mm - Fire

Styleknit ground floor front

PASS



Non-critical defect

ID: 870 [↗](#)

Added: 19th Apr 2024 4:45PM

Last Verified: 19th Apr 2024 4:45PM

Description:

Hose reel is not accessible/obstructed

Resolution:

Technician to investigate cause of issue and rectify where possible (excluding parts)

Quote: **ACTIONED** [↗](#)



Click photos to enlarge

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Signatures

Js

Company Accreditations: