

SERVICE REPORT

Australian Unity - Campbell Place Residential (RC)

2 Carramar Avenue
 Glen Waverley
 Victoria 3150

Report Number R-00930

Reference CAMB-RC2400668

Service Date: 4th September 2024

Scope of Works

CAMB-RC2400668

0	Critical Defects	A defect that renders a system inoperative.
0	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.
16	Passed Assets	

Servicing Summary

Service	Asset	Quantity
Fire Detection Systems - FIP: Monthly	06 - Fire Detection Systems - Panels	1

Maintenance

Fire Detection Systems - FIP: Monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset

Status


001 - Fire Detection Panel Notifier -
3030

Basement Level

PASS



Photos






Click photos to enlarge

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Signatures

		
Js	Js	Client Js

Company Accreditations: