

SERVICE REPORT

<p>Australian Unity - Campbell Place Residential (RC)</p> <p>2 Carramar Avenue Glen Waverley Victoria 3150</p>	<p>Report Number R-01731</p> <p>Reference</p> <p>Service Date: 6th November 2024</p>
---	---

Scope of Works

Fire Detection Systems - FIP: Monthly (1)

0	Critical Defects	A defect that renders a system inoperative.
0	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.
19	Passed Assets	

Servicing Summary

Service	Asset	Quantity
Fire Detection Systems - FIP: Monthly	06 - Fire Detection Systems - Panels	1

Maintenance

Fire Detection Systems - FIP: Monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset

Status

001 - Fire Detection Panel Notifier -
3030

Basement Level

PASS



Photos



Click photos to enlarge

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician

Date/Time

Accreditations

Signature

Mike Alford

6th Nov 2024
4:38PM

Company Accreditations: