

## SERVICE REPORT

<p><b>Australian Unity - Campbell Place Residential (RC)</b></p> <p>2 Carramar Avenue        Glen Waverley        Victoria 3150</p>	<p><b>Report Number R-00449</b></p> <p><b>Reference CAMB-RC2400509</b></p> <p><b>Service Date: 9th July 2024</b></p>
---	--

<b>Scope of Works</b>	
06 - Fire Detection Systems - FIP (2012): Monthly (1)	

<b>0 Critical Defects</b>	A defect that renders a system inoperative.
<b>0 Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>0 Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0 Recommendations</b>	A modification suggested to improve the system performance.
<b>0 Informational Notes</b>	Detailed advice or general comment.
<b>2 Passed Assets</b>	

<b>Servicing Summary</b>		
Service	Asset	Quantity
Fire Detection Systems - FIP: Monthly	06 - Fire Detection Systems - Panels	1

## Maintenance

<b>Fire Detection Systems - FIP: Monthly</b>		
AS1851-2012 (a1) - Routine service of fire protection systems and equipment		
Asset	Status	
001 - Fire Detection Panel	Basement Level	<span style="background-color: #27ae60; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>

## Logbooks



### 06 - Fire Detection Systems [↗](#)

Classic Logbook



### 03 - Fire pumpsets [↗](#)

Classic Logbook



### 02 - Automatic fire sprinkler systems [↗](#)

Classic Logbook

## Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Mike Alford	9th Jul 2024 1:46PM		

### Company Accreditations: