

## SERVICE REPORT

<b>The Kinson</b>  <b>452 Saint Kilda Road</b> <b>Melbourne</b> <b>Victoria 3004</b>	<b>Report Number R-00337</b> <b>Reference</b> <b>Service Date: 11th May 2024</b>
--------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------

Scope of Works
06 - Fire Detection Systems - FIP (2012): Annual (1)
06 - Fire Detection Systems - FIP (2012): Annual - Survey (1)

<b>0</b>	<b>Critical Defects</b>	A defect that renders a system inoperative.
<b>1</b>	<b>Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>0</b>	<b>Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0</b>	<b>Recommendations</b>	A modification suggested to improve the system performance.
<b>0</b>	<b>Informational Notes</b>	Detailed advice or general comment.

Servicing Summary		
Service	Asset	Quantity
06 - Fire Detection Systems - FIP (2012): Annual - Survey	06 - Fire Detection Systems - Panels	1
06 - Fire Detection Systems - FIP (2012): Annual	06 - Fire Detection Systems - Panels	1

## Maintenance

### 06 - Fire Detection Systems - FIP (2012): Annual - Survey

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

#### Asset

#### Status

15519

Ground, Sub FIP, Main FIP Room

FAIL

#### Non-critical defect

ID: 818 [↗](#)

Added: 18th Apr 2024 4:35PM

Last Verified: 18th Apr 2024 4:37PM

#### Description:

Common/general visual/audible indications do not operate  
Following devices in fault:L1 D155L1 D155.1L2 D12L2 D169L2 D169.1

#### Resolution:

Technician to investigate cause of issue and rectify where possible (excluding parts)

#### Location:

FIP

### 06 - Fire Detection Systems - FIP (2012): Annual

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

#### Asset

#### Status

15519

Ground, Sub FIP, Main FIP Room

FAIL

#### Non-critical defect

ID: 818 [↗](#)

Added: 18th Apr 2024 4:35PM

Last Verified: 18th Apr 2024 4:37PM

#### Description:

Common/general visual/audible indications do not operate  
Following devices in fault:L1 D155L1 D155.1L2 D12L2 D169L2 D169.1

#### Resolution:

Technician to investigate cause of issue and rectify where possible (excluding parts)

#### Location:

FIP

## Logbooks



Fusion Sub FIP [↗](#)

Classic Logbook

## Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Fire Technician	11th May 2024 6:53AM		
Mike Alford	11th May 2024 6:53AM		

## Signatures



Denim

### Company Accreditations: