

SERVICE REPORT

Australian Unity - Campbell Place Residential (RC)

**2 Carramar Avenue
Glen Waverley
Victoria 3150**

Report Number R-00653

Reference CAMB-RC2400593

Service Date: 13th August 2024

Scope of Works

CAMB-RC2400593 - Fire Detection Systems - FIP: Monthly (1)

0	Critical Defects	A defect that renders a system inoperative.
0	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.
2	Passed Assets	

Servicing Summary

Service	Asset	Quantity
Fire Detection Systems - FIP: Monthly	06 - Fire Detection Systems - Panels	1

Maintenance

Fire Detection Systems - FIP: Monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset	Status
001 - Fire Detection Panel Basement Level	PASS

Logbooks



06 - Fire Detection Systems [↗](#)

Classic Logbook



03 - Fire pumpsets [↗](#)

Classic Logbook



02 - Automatic fire sprinkler systems [↗](#)

Classic Logbook

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Company Accreditations: