

SERVICE REPORT

Styleknit	Report Number R-00230
Factory 10, 35 Dunlop Road	Reference
Mulgrave	Service Date:
Victoria 3170	

Scope of Works
15 - Emergency escape lighting and exit signs (2012): Six-monthly (0)

0	Critical Defects	A defect that renders a system inoperative.
2	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.

Servicing Summary		
Service	Asset	Quantity
15 - Emergency escape lighting and exit signs (2012): Six-monthly	15 - Emergency - Exit Signs	2

Maintenance

15 - Emergency escape lighting and exit signs (2012): Six-monthly

AS2293.2-2019 - Emergency escape lighting and exit signs for buildings

Asset

Status

002 - Exit Sign Jumbo (Wall Mount) -
Exit

Styleknit ground floor

FAIL

Non-critical defect

ID: 876 [↗](#)

Added: 23rd Apr 2024 4:39PM

Last Verified: 23rd Apr 2024 4:40PM

Description:

Emergency luminaire / exit sign not operating as required

Resolution:



Click photos to enlarge

001 - Exit Sign Quick Fit (Wall Mount) -
Exit

Styleknit 1st floor office

FAIL

Non-critical defect

ID: 875 [↗](#)

Added: 23rd Apr 2024 4:39PM

Last Verified: 23rd Apr 2024 4:39PM

Description:

Emergency luminaire / exit sign not operating as required

Resolution:



Click photos to enlarge

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Company Accreditations: