

SERVICE REPORT

Styleknit	Report Number R-00221
Factory 10, 35 Dunlop Road	Reference
Mulgrave	Service Date:
Victoria 3170	

Scope of Works
09 - Fire Hose Reels (2012): Six-monthly (1)

0	Critical Defects	A defect that renders a system inoperative.
1	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.

Servicing Summary		
Service	Asset	Quantity
09 - Fire Hose Reels (2012): Six-monthly	09 - Fire Hose Reels	1

Maintenance

09 - Fire Hose Reels (2012): Six-monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset

Status

007 - Hose Reel 36m - 19mm - Fire

Stylenit ground floor front

FAIL



Click photos to enlarge

Non-critical defect

ID: 870 [↗](#)

Added: 19th Apr 2024 4:45PM

Last Verified: 19th Apr 2024 4:45PM

Description:

Hose reel is not accessible/obstructed

Resolution:

Technician to investigate cause of issue and rectify where possible (excluding parts)



Click photos to enlarge

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Company Accreditations: