

SERVICE REPORT

Styleknit	Report Number R-00218
11/35 Dunlop Rd, Mulgrave VIC 3170, Australia	Reference
	Service Date: 19th April 2024

Scope of Works

Path of Travel & Discharge to Exit (2012): Annual (0)

0 Critical Defects	A defect that renders a system inoperative.
0 Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0 Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0 Recommendations	A modification suggested to improve the system performance.
0 Informational Notes	Detailed advice or general comment.

Servicing Summary

Service	Asset	Quantity
Path of Travel & Discharge to Exit (2012): Annual	12 - Path of Travel & Discharge to Exit	2

Maintenance

Path of Travel & Discharge to Exit (2012): Annual

Asset	Status
001 - Path of Travel & Discharge to Exit Exit Door Micra air factory exit door	PASS
002 - Path of Travel & Discharge to Exit Exit Door Affinity ground floor office	PASS

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Company Accreditations: