

## SERVICE REPORT

<p><b>Australian Unity - Walmsley Community Centre</b></p> <p>Greeves Drive        Kilsyth        Victoria 3137</p>	<p><b>Report Number R-02509</b></p> <p><b>Reference WALMSLY-2401481</b></p> <p><b>Service Date: 4th October 2024</b></p>
---	--

<b>Scope of Works</b>
Fire Detection Systems - FIP: Monthly (1)

<b>0</b>	<b>Critical Defects</b>	A defect that renders a system inoperative.
<b>0</b>	<b>Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>1</b>	<b>Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0</b>	<b>Recommendations</b>	A modification suggested to improve the system performance.
<b>0</b>	<b>Informational Notes</b>	Detailed advice or general comment.
<b>1</b>	<b>Passed Assets</b>	

<b>Servicing Summary</b>		
<b>Service</b>	<b>Asset</b>	<b>Quantity</b>
Fire Detection Systems - FIP: Monthly	06 - Fire Detection Systems - Panels	1

## Maintenance

### Fire Detection Systems - FIP: Monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

#### Asset

#### Status

001 - Fire Detection Panel Ampac -  
Firefinder Plus

Serial: 2106762/03  
Entry

PASS



#### Non-conformance

Added: 3rd Apr 2024 8:35AM

ID: 699 [↗](#)

#### Description:

Update block plan to include zone list.

#### Resolution:

Quote to rectify defect required

Quote: **ACTIONED** [↗](#)

## Photos



Click photos to enlarge

## Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

#### Technician

#### Date/Time

#### Accreditations

#### Signature

Mike Alford

4th Oct 2024  
12:41PM

## Signatures



Js

### Company Accreditations: