

## SERVICE REPORT

<p><b>Styleknit</b></p> <p><b>Factory 10, 35 Dunlop Road          Mulgrave          Victoria 3170</b></p>	<p><b>Report Number R-00229</b></p> <p><b>Reference</b></p> <p><b>Service Date:</b></p>
---	---

Scope of Works	
11 - Fire Blankets (2012): Six-monthly (0)	

<b>0</b>	<b>Critical Defects</b>	A defect that renders a system inoperative.
<b>1</b>	<b>Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>0</b>	<b>Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0</b>	<b>Recommendations</b>	A modification suggested to improve the system performance.
<b>0</b>	<b>Informational Notes</b>	Detailed advice or general comment.

Servicing Summary		
Service	Asset	Quantity
11 - Fire Blankets (2012): Six-monthly	11 - Fire Blankets	1

## Maintenance

### 11 - Fire Blankets (2012): Six-monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

#### Asset

#### Status

002 - Fire Blanket 1.0M x 1.0M

Stylenit ground floor

FAIL



Click photos to enlarge

#### Non-critical defect

ID: 859 [↗](#)

Added: 19th Apr 2024 4:15PM

Last Verified: 19th Apr 2024 4:16PM

#### Description:

Fire blanket not installed

#### Resolution:

Technician to investigate cause of issue and rectify where possible (excluding parts)



Click photos to enlarge

## Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

#### Company Accreditations: