

SERVICE REPORT

Australian Unity - The Grace

114 Albert Road
Melbourne
Victoria 3004

Report Number R-01421

Reference GRACE-2400471

Service Date: 7th November 2024

Scope of Works

Fire Detection Systems - FIP: Monthly (1)

0	Critical Defects	A defect that renders a system inoperative.
1	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
1	Informational Notes	Detailed advice or general comment.
0	Passed Assets	

Servicing Summary

Service	Asset	Quantity
Fire Detection Systems - FIP: Monthly	06 - Fire Detection Systems - Panels	1

Maintenance

Fire Detection Systems - FIP: Monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset	Status
001 - Fire Detection Panel Notifier - 3030	Ground Floor Fire Control Room FAIL



Non-critical defect Added: 8th Jul 2024 8:37AM
ID: 1061 [↗](#)

Description:
Intermittent Fault Annunciator Panel (Zone Display Module)

Resolution:
Stage 1 Panel, to be rectified by Leemark

Location:
Ground Floor Main Panel

Informational Added: 8th Jul 2024 8:38AM
ID: 1062 [↗](#)

Description:
20 x Isolations on Stage 1 Panel

Resolution:
To be rectified by Leemark

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.