

SERVICE REPORT

Australian Unity - Walmsley Community Centre

Greeves Drive
 Kilsyth
 Victoria 3137

Report Number R-00342
 Reference WALMSLY-2400722
 Service Date:

Scope of Works

Path of Travel & Discharge to Exit (2012): Quarterly (5)

0	Critical Defects	A defect that renders a system inoperative.
0	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.

Servicing Summary

Service	Asset	Quantity
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	5

Maintenance

Path of Travel & Discharge to Exit (2012): Quarterly

Asset	Status
005 - Path of Travel & Discharge to Exit Exit Door Kitchen	PASS

Asset		Status
004 - Path of Travel & Discharge to Exit Exit Door	North East	PASS
003 - Path of Travel & Discharge to Exit Path of Travel	Entrance, North East & Rear Kitchen	PASS
002 - Path of Travel & Discharge to Exit Discharge from Exit	Entrance, North East & Rear Kitchen	PASS
001 - Path of Travel & Discharge to Exit Exit Door	Entrance	PASS

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Fire Technician	None		
Mike Alford	None		

Company Accreditations: