

## SERVICE REPORT

<b>Styleknit</b>	<b>Report Number R-01735</b>
<b>11/35 Dunlop Rd, Mulgrave VIC 3170, Australia</b>	<b>Reference</b>
	<b>Service Date:</b>

### Scope of Works

15 - Emergency escape lighting and exit signs (2012): Annual (3)

<b>0</b>	<b>Critical Defects</b>	A defect that renders a system inoperative.
<b>1</b>	<b>Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>0</b>	<b>Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0</b>	<b>Recommendations</b>	A modification suggested to improve the system performance.
<b>0</b>	<b>Informational Notes</b>	Detailed advice or general comment.
<b>3</b>	<b>Passed Assets</b>	

### Servicing Summary

Service	Asset	Quantity
15 - Emergency escape lighting and exit signs (2012): Annual	15 - Emergency - Exit Signs	3

### Maintenance

**15 - Emergency escape lighting and exit signs (2012): Annual**  
 AS2293.2-2019 - Emergency escape lighting and exit signs for buildings

Asset	Status
<b>003 - Exit Sign Quick Fit (Ceiling Mount) - Exit</b>	Affinity ground floor office <span style="background-color: green; color: white; padding: 2px 5px;">PASS</span>

Asset

Status



Non-critical defect

ID: 854 [↗](#)

Added: 19th Apr 2024 3:43PM

Last Verified: 19th Apr 2024 3:43PM

Description:

Emergency luminaire / exit sign not installed

Resolution:

Quote: **ACTIONED** [↗](#)



Click photos to enlarge

002 - Exit Sign Quick Fit (Wall Mount) - Exit

Affinity 1st floor office

**PASS**

001 - Exit Sign Quick Fit (Wall Mount) - Exit

Micra air factory exit door

**PASS**

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Service Technician	None		
Mike Alford	None		

Company Accreditations: