

## SERVICE REPORT

**Australian Unity - Geelong Grove Community Centre**

**50 Barwarre Road  
 Marshall  
 Victoria 3216**

**Report Number R-00571**

**Reference GEELONG-2400528**

**Service Date: 14th August 2024**

### Scope of Works

Portable & Wheeled Fire Extinguishers

0	<b>Critical Defects</b>	A defect that renders a system inoperative.
0	<b>Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
1	<b>Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
0	<b>Recommendations</b>	A modification suggested to improve the system performance.
0	<b>Informational Notes</b>	Detailed advice or general comment.
44	<b>Passed Assets</b>	

### Servicing Summary

Service	Asset	Quantity
10 - Portable and Wheeled Fire Extinguishers (2012): Annual	10 - Fire Extinguishers - Portable	5

## Maintenance

### 10 - Portable and Wheeled Fire Extinguishers (2012): Annual

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset		Status
006 - Fire Extinguisher DCP AB(E) 2.5KG	Workshop	PASS
005 - Fire Extinguisher DCP AB(E) 2.5KG	Men's Shed	PASS
004 - Fire Extinguisher DCP AB(E) 2.5KG	Cottage	PASS
002 - Fire Extinguisher DCP AB(E) 2.5KG	Community Centre, out Consult Rm	PASS
		
001 - Fire Extinguisher DCP AB(E) 2.5KG	Community Centre, Library	PASS
		

## Repairs

### 001 - Fire Extinguisher DCP AB(E) 2.5KG

Community Centre, Library

PASS



Click photos to enlarge

**RESOLVED**

**Non-conformance**

Added: 14th Aug 2024 8:07AM

ID: 1318 [↗](#)

Last Verified: 14th Aug 2024 8:07AM

**Description:**

Location sign is missing / visible

**Before**

**After**



Click photos to enlarge

**Parts/Labour**

**Quantity**

**Signoff**

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

**Technician**

**Date/Time**

**Accreditations**

**Signature**

Mike Alford

14th Aug 2024  
12AM

**Company Accreditations:**