

SERVICE REPORT

<p>Australian Unity - Walmsley Community Centre</p> <p>Greeves Drive Kilsyth Victoria 3137</p>	<p>Report Number R-00861</p> <p>Reference WALMSLY-2401337</p> <p>Service Date: 4th September 2024</p>
---	--

Scope of Works
Fire Detection Systems - FIP: Monthly (1)

0 Critical Defects	A defect that renders a system inoperative.
1 Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
1 Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0 Recommendations	A modification suggested to improve the system performance.
0 Informational Notes	Detailed advice or general comment.
1 Passed Assets	

Servicing Summary		
Service	Asset	Quantity
Fire Detection Systems - FIP: Monthly	06 - Fire Detection Systems - Panels	1

Maintenance

Fire Detection Systems - FIP: Monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset

Status

001 - Fire Detection Panel Ampac -
Firefinder Plus

Serial: 2106762/03
Entry

PASS



Non-conformance

Added: 3rd Apr 2024 8:35AM

ID: 699 [↗](#)

Description:

Update block plan to include zone list.

Resolution:

Quote to rectify defect required

Quote: **ACTIONED** [↗](#)

Repairs

001 - Fire Detection Panel Ampac - Firefinder Plus

Entry

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 3rd Jun 2024 3:18PM

ID: 954 [↗](#)

Last Verified: 3rd Jun 2024 3:19PM

Description:

Battery past service life



Click photos to enlarge

Parts/Labour

Quantity

Photos



Click photos to enlarge

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Service Technician	4th Sep 2024 1:39PM		

Signatures

Js

Company Accreditations: