

SERVICE REPORT

<p>Heritage Aged Care - Twin Parks Reservoir</p> <p>33 Blake Street Reservoir Victoria 3073</p>	<p>Report Number R-00782</p> <p>Reference</p> <p>Service Date: 12th September 2024</p>
---	---

Scope of Works	
Emergency & exit lights	

0	Critical Defects	A defect that renders a system inoperative.
67	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
4	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.
230	Passed Assets	

Servicing Summary		
Service	Asset	Quantity
15 - Emergency escape lighting and exit signs (2012): Six-monthly	15 - Emergency - Exit Signs	74
15 - Emergency escape lighting and exit signs (2012): Six-monthly	15 - Emergency - Lighting	85

Maintenance

15 - Emergency escape lighting and exit signs (2012): Six-monthly

AS2293.2-2019 - Emergency escape lighting and exit signs for buildings

Asset	Status
-------	--------

EX G.31 - Exit Sign Pyramid (Ceiling Mount) - Exit	
---	--

Theatre seats east

PASS



EX 1.23 - Exit Sign Quick Fit (Ceiling Mount) - Exit	
---	--

East Doors into library from J corridor

PASS



EX 1.21 - Exit Sign Quick Fit (Ceiling Mount) - Exit	
---	--

East Next to staff toilet

PASS



EX 1.9 - Exit Sign Quick Fit (Ceiling Mount) - Exit	
--	--

East Intersection of corridor k and m

PASS



EX 1.8 - Exit Sign Quick Fit (Ceiling Mount) - Exit	
--	--

East Adjacent to J3

PASS



EX 1.26 - Exit Sign Quick Fit (Ceiling Mount) - Exit	
---	--

Adjacent to F16 east inside the stair case

PASS




Asset		Status
EX G.9 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Adjacent to H3 east	PASS
		
EX G.3 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Adjacent to room D3(east)	PASS
		
EX 1.25 - Exit Sign Quick Fit (Ceiling Mount) - Exit	In stair case adjacent to room D3(east)	PASS
		
31M.2 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Adjacent to B5	PASS
		
EX 1.20 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Opposite to Infection control trolley and control kits room	PASS
		
EX 1.3 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Adjacent to J10	PASS
		
33M.25 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Nurse station west wing	PASS

Asset		Status
		
32 M-4 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Nurse station west wing	FAIL
		
<div style="background-color: #fff9c4; padding: 10px;"> <p>Non-critical defect Added: 12th Sep 2024 2:43PM</p> <p>ID: 1595 ↗ Last Verified: 12th Sep 2024 2:43PM</p> <p>Description: Emergency luminaire / exit sign not operating as required</p> <p>Resolution:</p> <p>Location: Adjacent to nurse station west wing</p>  <p>Click photos to enlarge</p> </div>		
W EX 1.1 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East In staff room upstairs	PASS
		
EX1.19 - Exit Sign Quick Fit (Ceiling Mount) - Exit	North east fire stairs	PASS
		
EX 1.4 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Adjacent to J9	PASS
		
EX G.21 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Adjacent to room F18	PASS

Asset		Status
		
EX G.4 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Right of D9 east	PASS
		
EX G.12 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East In between rooms G1 and G11 in the intersection of corridor.	PASS
		
EX G.1 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Adjacent to room D5 (east)	PASS
		
7B.11 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Adjacent to A8 above exit door	PASS
		
EX G.14 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Dining room near bar	PASS
		
EX 1.2 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East J wing corridor next to the stair case	PASS
		

Asset		Status
EX 1.16 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Adjacent to L5	PASS
		
EX 1.17 - Exit Sign Pyramid (Ceiling Mount) - Exit	East North end of L block	PASS
		
EX 1.10 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Intersection of corridor k and m	PASS
		
EX G.29 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Adjacent to G3 east	PASS
		
31M.1 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West South zone 5 lounge	PASS
		
33M.5 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Adjacent to staff toilets	PASS
		
EX G.7 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Reception next to stairs	PASS

Asset		Status
 <p>EX G.25 - Exit Sign Quick Fit (Wall Mount) - Exit</p>	Private lounge near main east entrance	PASS
 <p>EX G.26 - Exit Sign Quick Fit (Ceiling Mount) - Exit</p>	East Private lounge near dining room	PASS
 <p>EX G.30 - Exit Sign Quick Fit (Ceiling Mount) - Exit</p>	Theatre seats east	PASS
 <p>EX 1.1 - Exit Sign Quick Fit (Ceiling Mount) - Exit</p>	East J wing corridor next to the stair case	PASS
 <p>EX 1.22 - Exit Sign Quick Fit (Ceiling Mount) - Exit</p>	East Library adjacent to conference room	PASS
 <p>G EX.33 - Exit Sign Quick Fit (Ceiling Mount) - Exit</p>	Adjacent to hair salon	PASS
		

Asset		Status
EX 1.15 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Adjacent to L16	PASS
		
EX 1.12 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Adjacent to L14 in front of fire door	PASS
		
EX G.22 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Adjacent to room F4, east	PASS
		
EX G.19 - Exit Sign Jumbo (Ceiling Mount) - Exit	Adjacent to F8 east	PASS
		
EX G.18 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Adjacent to F17 east	PASS
		
EX G.16 - Exit Sign Quick Fit (Ceiling Mount) - Exit	The right of F12 east	PASS
		
EX G.11 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Adjacent to E5 east	PASS

Asset	Status
	
EX G.10A - Exit Sign Quick Fit (Ceiling Mount) - Exit	Opposite H11 east PASS
	
EX G.5 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Left of D10 east PASS
	
6A.7 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Near C1 PASS
	
6A.8 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Entrance into lounge PASS
	
6A.5 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Adjacent to C12 PASS
	
6A.4 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Adjacent to C14 on opposite side of the smoke door PASS
	

Asset		Status
31M.3 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Adjacent to B8	PASS
		
7B.10 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Adjacent to laundry west	PASS
		
33.5 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Lounge area adjacent to B corridor	FAIL
		
<div style="background-color: #fff9c4; padding: 10px;"> <p>Non-critical defect Added: 12th Sep 2024 2:43PM</p> <p>ID: 1596 ↗ Last Verified: 12th Sep 2024 2:44PM</p> <p>Description: Emergency luminaire / exit sign not operating as required</p> <p>Resolution:</p> <p>Location: West wing dinning</p>  <p>Click photos to enlarge</p> </div>		
EX 1.11 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Adjacent to L9	PASS
		
EX G.23 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Opposite laundry	PASS
		

Asset		Status
EX G.10 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East In between rooms H11 and H10 in the intersection of corridor.	PASS
		
E EX.1.24 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Inside stair case that is adjacent to east reception	PASS
		
E G.6 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Reception next to stairs	PASS
		
E EX G.8 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East wing main entrance	PASS
		
EX 1.14 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Just outside of Library near the general store	PASS
		
EX 1.18 - Exit Sign Pyramid (Ceiling Mount) - Exit	East North end of L block above fire door	PASS
		
EX 1.13 - Exit Sign Quick Fit (Ceiling Mount) - Exit	East Adjacent to L14	PASS

Asset	Status
	
EX 1.5 - Exit Sign Quick Fit (Ceiling Mount) - Exit East Adjacent to K2	PASS
	
EX G.24 - Exit Sign Quick Fit (Ceiling Mount) - Exit East Opposite laundry	PASS
	
EX 1.7 - Exit Sign Quick Fit (Ceiling Mount) - Exit East Adjacent to J6	PASS
	
EX 1.6 - Exit Sign Quick Fit (Ceiling Mount) - Exit East Adjacent to J8	PASS
	
EX G.20 - Exit Sign Jumbo (Ceiling Mount) - Exit East Adjacent to room F18	PASS
	
EX G.27 - Exit Sign Quick Fit (Ceiling Mount) - Exit Adjacent to G7 east	PASS
	

Asset		Status
EX G.17 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Adjacent to F16 east	PASS
		
G EX.34 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Adjacent to F15 east	PASS
		
EX G.2 - Exit Sign Quick Fit (Ceiling Mount) - Exit	Adjacent to room D7(east)	PASS
		
6A.6 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Adjacent to C12 above outside exit door	PASS
		
7B.12 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Adjacent to A8	PASS
		
7B.9 - Exit Sign Quick Fit (Ceiling Mount) - Exit	West Adjacent to A16	PASS
		
EM G.24 - Emergency Lighting Spitfire (Flush Mount)	Adjacent to room G3	PASS

Asset	Status
-------	--------



EM 1.2 - Emergency Lighting Spitfire (Flush Mount)

East J wing corridor next to the stair case

FAIL



Non-critical defect

ID: 1578 [↗](#)

Added: 12th Sep 2024 8:51AM

Last Verified: 12th Sep 2024 8:51AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Resolution:

Location:

Level 1 adjacent to visitor toilet at reception



Click photos to enlarge

Non-critical defect

ID: 1569 [↗](#)

Added: 12th Sep 2024 8:03AM

Last Verified: 12th Sep 2024 8:04AM

Description:

Emergency luminaire / exit sign not operating as required

Resolution:

Location:

Level 1 adjacent to visitor toilet at reception



Click photos to enlarge

EM G.13 - Emergency Lighting Spitfire (Flush Mount)

Adjacent to F17 east

PASS




EM G.30 - Emergency Lighting Spitfire (Flush Mount)

East Staff room at the back of theatre seats

PASS

Asset	Status
 <p>EM G1.30 - Emergency Lighting 4FT - Single Weatherproof Batten Adjacent to F16 east inside the stair case</p>	<p>PASS</p>
 <p>EM G.2 - Emergency Lighting Spitfire - (Surface Mount) East adjacent to room D3</p>	<p>PASS</p>
 <p>EM 1.17 - Emergency Lighting 4FT - Single Weatherproof Batten East North east fire stairs</p>	<p>PASS</p>
 <p>EM G.9 - Emergency Lighting Spitfire - (Surface Mount) Adjacent to E6 east</p>	<p>FAIL</p>
<div style="background-color: #fff9c4; padding: 10px;"> <p>Non-critical defect Added: 12th Sep 2024 1:10PM ID: 1594 ↗ Last Verified: 12th Sep 2024 1:10PM</p> <p>Description: Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes</p> <p>Resolution:</p> <p>Location: Adjacent to E6</p>  <p>Click photos to enlarge</p> </div>	
<p>EM1.12 - Emergency Lighting Spitfire (Flush Mount) East Adjacent to L7</p>	<p>PASS</p>

Asset	Status
	
EM 1.29 - Emergency Lighting 4FT - Single Weatherproof Batten	East Fire stairwell adjacent to J3 PASS
	
EM G.26 - Emergency Lighting Spitfire (Flush Mount)	Private lounge near main east entrance PASS
	
6A.27 - Emergency Lighting Spitfire (Flush Mount)	West Adjacent to C14 PASS
	
33M.22 - Emergency Lighting Spitfire (Flush Mount)	West Lounge area adjacent to B corridor PASS
	
W EM 1.3 - Emergency Lighting Spitfire (Flush Mount)	East In staff room upstairs PASS
	
6A.26 - Emergency Lighting Spitfire (Flush Mount)	West Adjacent to C10 PASS
	

Asset		Status
EM 1.11 - Emergency Lighting Spitfire (Flush Mount)	East Adjacent to L12	PASS
		
7B.29 - Emergency Lighting Spitfire (Flush Mount)	West Adjacent to A10	PASS
		
EM 1.7 - Emergency Lighting Spitfire (Flush Mount)	East Adjacent to K5	PASS
		
EM 1.23A - Emergency Lighting Spitfire (Flush Mount)	Library east	PASS
EM 1.20 - Emergency Lighting Spitfire (Flush Mount)	East adjacent to Kitchen	PASS
		
EM1.16 - Emergency Lighting 4FT - Single Weatherproof Batten	East North east fire stairs	PASS
		
EM 1.29 - Emergency Lighting 4FT - Single Weatherproof Batten	East Fire stairwell adjacent to J3	PASS
		
EM G1.31 - Emergency Lighting 4FT - Single Weatherproof Batten	Adjacent to F16 east inside the stair case	PASS

Asset	Status
	
EM G.22 - Emergency Lighting Spitfire (Flush Mount) Adjacent to G6 east	PASS
	
EM G.34 - Emergency Lighting Spitfire - (Surface Mount) Meeting room near reception east.	FAIL
	
<div style="background-color: #fff9c4; padding: 10px;"> <p>Non-critical defect Added: 28th Mar 2024 8:59AM ID: 519 ↗ Last Verified: 28th Mar 2024 8:59AM</p> <p>Description: Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes</p> <p>Resolution: Quote: DECLINED ↗</p>  <p>Click photos to enlarge</p> </div>	
31M.21 - Emergency Lighting Spitfire (Flush Mount) West Adjacent to B7	PASS
	
EX G.4 - Emergency Lighting Spitfire - (Surface Mount) East Reception in front of elevator	PASS
	
EM 1.4 - Emergency Lighting Spitfire (Flush Mount) East Adjacent to J7	FAIL

Asset	Status
-------	--------



Non-critical defect
ID: 1577 [↗](#)

Added: 12th Sep 2024 8:49AM
Last Verified: 12th Sep 2024 8:50AM

Description:
Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Resolution:

Location:
Adjacent to J3



Click photos to enlarge

Non-critical defect
ID: 1572 [↗](#)

Added: 12th Sep 2024 8:13AM
Last Verified: 12th Sep 2024 8:14AM

Description:
Emergency luminaire / exit sign not operating as required

Resolution:

Location:
Level 1 adjacent to J3



Click photos to enlarge

**EM 1.21 - Emergency Lighting Spitfire
(Flush Mount)**

East Dining area adjacent to kitchen

PASS



**EM 1.10 - Emergency Lighting Spitfire
(Flush Mount)**

East Adjacent to L9

PASS



**EM 1.6 - Emergency Lighting Spitfire
(Flush Mount)**

East Adjacent to M3

PASS

Asset	Status
	
EM 1.5 - Emergency Lighting Spitfire (Flush Mount) East Adjacent to J8	PASS
	
EM G.10 - Emergency Lighting Spitfire (Flush Mount) Adjacent to doctors room east ground	PASS
	
EM G.15 - Emergency Lighting Spitfire (Flush Mount) East Adjacent to F7	PASS
	
156 - Emergency Lighting Spitfire (Flush Mount) Adjacent to D11	PASS
33M.23 - Emergency Lighting Spitfire (Flush Mount) West Adjacent to kitchen serve area	PASS
	
EM G.11 - Emergency Lighting Spitfire (Flush Mount) Left of bar east	PASS
	
EM G.29 - Emergency Lighting Spitfire - (Surface Mount) Main Dining room east	PASS

Asset	Status
 <p>EM 1.19 - Emergency Lighting Spitfire (Flush Mount) East Adjacent to drug treatment room</p>	<p>PASS</p>
 <p>1.14 - Emergency Lighting Spitfire (Flush Mount) East Adjacent to bath room/spa</p>	<p>PASS</p>
<div style="background-color: #fff9c4; padding: 10px;"> <p>Non-critical defect Added: 28th Mar 2024 9:29AM ID: 561 ↗ Last Verified: 28th Mar 2024 9:29AM</p> <p>Description: Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes</p> <p>Resolution: Quote: DECLINED ↗</p>  <p>Click photos to enlarge</p> </div>	
<p>EM 1.9 - Emergency Lighting Spitfire (Flush Mount) East Adjacent to M6</p> 	<p>PASS</p>
<p>EM 1.22 - Emergency Lighting Spitfire (Flush Mount) East Adjacent to K8</p> 	<p>PASS</p>
<p>EM 1.8 - Emergency Lighting Spitfire (Flush Mount) East Adjacent to K7</p>	<p>PASS</p>

Asset	Status
-------	--------



EM1.3 - Emergency Lighting Spitfire (Flush Mount)

East Adjacent to J2

PASS



EM G.32 - Emergency Lighting Spitfire - (Surface Mount)

Theatre east

PASS



Non-critical defect Added: 28th Mar 2024 9:18AM
 ID: 548 [↗](#) Last Verified: 28th Mar 2024 9:18AM

Description:
 Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Resolution:
 Quote: **DECLINED** [↗](#)



Click photos to enlarge

EM G.1 - Emergency Lighting Spitfire - (Surface Mount)

Adjacent to room D7(east)

PASS



EM G.7 - Emergency Lighting Spitfire (Flush Mount)

Adjacent to room H3 (east)

PASS



EM G.8 - Emergency Lighting Spitfire (Flush Mount)

Adjacent to H3 east

PASS

Asset	Status
 <p>7B.30 - Emergency Lighting Spitfire (Flush Mount) West Adjacent to A7</p>	PASS
 <p>EM G.12 - Emergency Lighting Spitfire (Flush Mount) Adjacent to F12 east</p>	PASS
<div style="background-color: #fff9c4; padding: 10px;"> <p>Non-critical defect Added: 28th Mar 2024 9:25AM ID: 554 ↗ Last Verified: 28th Mar 2024 9:25AM</p> <p>Description: Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes</p> <p>Resolution: Quote: DECLINED ↗</p> <div style="display: flex; justify-content: space-around;">   </div> <p><small>Click photos to enlarge</small></p> </div>	
<p>EM G.20 - Emergency Lighting Spitfire (Flush Mount) Adjacent to H8 east</p> 	PASS
<p>EM-G.5 - Emergency Lighting Spitfire - (Surface Mount) East reception</p> 	PASS
<p>6A.25 - Emergency Lighting Spitfire (Flush Mount) West Adjacent to C7</p>	PASS

Asset	Status
	
7B.28 - Emergency Lighting Spitfire (Flush Mount) West Adjacent to A1	PASS
	
158 - Emergency Lighting Spitfire (Flush Mount) West nurse station	PASS
32M.24 - Emergency Lighting Spitfire (Flush Mount) West Main lounge adjacent to C block	PASS
	
W EM 1.2 - Emergency Lighting Spitfire (Flush Mount) East In staff room upstairs adjacent go bathroom	PASS
	
EM 1.26 - Emergency Lighting 4FT - Single Weatherproof Batten East Inside of fire door into entrance stairwell	PASS
	
EM G.6 - Emergency Lighting Spitfire (Flush Mount) Adjacent to H15 east	PASS
	
EM G.14 - Emergency Lighting Spitfire (Flush Mount) Adjacent to F8 east	PASS

Asset	Status
	
EM G.25 - Emergency Lighting Spitfire - (Surface Mount) East adjacent to room G1	PASS
	
157 - Emergency Lighting Spitfire (Flush Mount) Adjacent to C3	PASS
31M.20 - Emergency Lighting Spitfire (Flush Mount) West South zone 5 lounge	PASS
	
32M.4 - Emergency Lighting Spitfire (Flush Mount) West Adjacent to staff toilets	PASS
	
EM 1.1 - Emergency Lighting Spitfire (Flush Mount) East Office in entrance foyer level 2	FAIL

Non-critical defect
ID: 1570 [↗](#)

Added: 12th Sep 2024 8:05AM
Last Verified: 12th Sep 2024 8:05AM

Description:
Emergency luminaire / exit sign not operating as required

Resolution:

Location:
Level 1 PPE storeroom



Click photos to enlarge

Asset	Status
-------	--------

<p>Non-critical defect ID: 585 ↗</p> <p>Description: Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes</p> <p>Resolution: Quote: DECLINED ↗</p> <div style="border: 1px solid #ccc; width: 100px; height: 100px; margin: 5px 0;">  </div> <p><small>Click photos to enlarge</small></p>	<p>Added: 28th Mar 2024 9:44AM Last Verified: 28th Mar 2024 9:44AM</p>
---	--

EM1.27 - Emergency Lighting 4FT - Single Weatherproof Batten	East Top of entrance fire stairwell	PASS
---	-------------------------------------	--



EM 1.24 - Emergency Lighting Spitfire (Flush Mount)	Library east	PASS
--	--------------	--



EM 1.25 - Emergency Lighting Spitfire (Flush Mount)	Conference room east	PASS
--	----------------------	--




EM 1.23B - Emergency Lighting Spitfire (Flush Mount)	Library east	PASS
---	--------------	--



EM 1.18 - Emergency Lighting Spitfire (Flush Mount)	East Dining area adjacent to nurse station	PASS
--	--	--



Asset		Status
EM 1.13 - Emergency Lighting Spitfire (Flush Mount)	East Adjacent to L5, and cleaners room	PASS
		
EM 1.15 - Emergency Lighting Spitfire (Flush Mount)	East adjacent to L20	PASS
		
EM G.31 - Emergency Lighting Spitfire (Flush Mount)	East Right of theatre seats	PASS
		
EM G.18 - Emergency Lighting Spitfire - (Surface Mount)	East Adjacent to laundry	PASS
		
EM G.17 - Emergency Lighting Spitfire - (Surface Mount)	East Adjacent to F5	PASS
		

Non-critical defect
ID: 1585 [↗](#)

Added: 12th Sep 2024 12:48PM
Last Verified: 12th Sep 2024 12:49PM

Description:
Emergency luminaire / exit sign not operating as required

Resolution:



Click photos to enlarge

Asset		Status
EM G.16 - Emergency Lighting Spitfire (Flush Mount)	Adjacent to room F18, east	PASS
		
EM G.23 - Emergency Lighting Spitfire (Flush Mount)	Adjacent to G11 east	PASS
		
EM G.21 - Emergency Lighting Spitfire (Flush Mount)	Adjacent to H7 east	PASS
		
<div style="background-color: #fff9c4; padding: 10px;"> <p data-bbox="124 1081 338 1108">Non-critical defect</p> <p data-bbox="124 1120 242 1146">ID: 1593 ↗</p> <p data-bbox="1094 1081 1490 1146" style="text-align: right;">Added: 12th Sep 2024 12:59PM Last Verified: 12th Sep 2024 1:01PM</p> <p data-bbox="124 1182 264 1209">Description:</p> <p data-bbox="124 1218 737 1245">Emergency luminaire / exit sign not operating as required</p> <p data-bbox="124 1267 255 1294">Resolution:</p> <div data-bbox="124 1303 225 1404">  </div> <p data-bbox="124 1413 322 1440">Click photos to enlarge</p> </div>		
EM G.19 - Emergency Lighting Spitfire (Flush Mount)	East Adjacent to H10 east	PASS
		
159 - Emergency Lighting Spitfire (Flush Mount)	Kitchen west	PASS
W EM 1.1 - Emergency Lighting Spitfire (Flush Mount)	East Top of staff area stairs	PASS

Asset	Status
-------	--------



EM G.3 - Emergency Lighting Spitfire (Flush Mount)

Adjacent of doors from the east to west area

FAIL



Non-critical defect
ID: 1597 [↗](#)

Added: 12th Sep 2024 2:46PM
Last Verified: 12th Sep 2024 2:46PM

Description:

Emergency luminaire / exit sign not operating as required

Resolution:

Location:

Adjacent to D2



Click photos to enlarge

EM G.27 - Emergency Lighting Spitfire - (Surface Mount)

Private lounge near main east entrance

PASS



EM G.33 - Emergency Lighting Spitfire - (Surface Mount)

East Opposite hairdresser

PASS



EM G.28 - Emergency Lighting Spitfire - (Surface Mount)

Private lounge near main east entrance

PASS



Repairs

156 - Emergency Lighting Spitfire (Flush Mount)

PASS

Adjacent to D11

RESOLVED Recommendation

Added: 5th Apr 2024 2:45PM

ID: 749 [↗](#)

Last Verified: 5th Apr 2024 2:45PM

Description:

Install a spitfire due to dark spots.

After



[Click photos to enlarge](#)

Parts/Labour

Quantity

157 - Emergency Lighting Spitfire (Flush Mount)

PASS

Adjacent to C3

RESOLVED Recommendation

Added: 5th Apr 2024 2:45PM

ID: 748 [↗](#)

Last Verified: 5th Apr 2024 2:45PM

Description:

Install a spitfire due to dark spots.

After



[Click photos to enlarge](#)

Parts/Labour

Quantity

158 - Emergency Lighting Spitfire (Flush Mount)

PASS

West nurse station

RESOLVED Recommendation

Added: 5th Apr 2024 2:44PM

ID: 747 [↗](#)

Last Verified: 5th Apr 2024 2:44PM

Description:

Install a spitfire due to dark spots.

After



[Click photos to enlarge](#)

Parts/Labour

Quantity

159 - Emergency Lighting Spitfire (Flush Mount)

PASS

Kitchen west

RESOLVED Recommendation

Added: 5th Apr 2024 2:41PM

ID: 746 [↗](#)

Last Verified: 5th Apr 2024 2:41PM

Description:

Install a spitfire due to dark spots.

After



Click photos to enlarge

Parts/Labour

Quantity

31M.2 - Exit Sign Quick Fit (Ceiling Mount) - Exit

PASS

West Adjacent to B5



Click photos to enlarge

RESOLVED Non-critical defect

Added: 28th Mar 2024 9:06AM

ID: 530 [↗](#)

Last Verified: 28th Mar 2024 9:07AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

31M.20 - Emergency Lighting Spitfire (Flush Mount)

PASS

West South zone 5 lounge



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:07AM

ID: 532 [↗](#)

Last Verified: 28th Mar 2024 9:07AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

31M.3 - Exit Sign Quick Fit (Ceiling Mount) - Exit

West Adjacent to B8

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:06AM

ID: 529 [↗](#)

Last Verified: 28th Mar 2024 9:06AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

32 M-4 - Exit Sign Quick Fit (Ceiling Mount) - Exit

West Nurse station west wing

FAIL



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:05AM

ID: 526 [↗](#)

Last Verified: 28th Mar 2024 9:05AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

32M.24 - Emergency Lighting Spitfire (Flush Mount)

West Main lounge adjacent to C block

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:04AM

ID: 524 [↗](#)

Last Verified: 28th Mar 2024 9:05AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

33.5 - Exit Sign Quick Fit (Ceiling Mount) - Exit

West Lounge area adjacent to B corridor

FAIL



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:05AM

ID: 527 [↗](#)

Last Verified: 28th Mar 2024 9:06AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

6A.25 - Emergency Lighting Spitfire (Flush Mount)

West Adjacent to C7

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:04AM

ID: 523 [↗](#)

Last Verified: 28th Mar 2024 9:04AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

6A.26 - Emergency Lighting Spitfire (Flush Mount)

West Adjacent to C10

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:05AM

ID: 528 [↗](#)

Last Verified: 28th Mar 2024 9:06AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge


Parts/Labour

Quantity

6A.27 - Emergency Lighting Spitfire (Flush Mount)

West Adjacent to C14

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:07AM

ID: 533 [↗](#)

Last Verified: 28th Mar 2024 9:07AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

6A.4 - Exit Sign Quick Fit (Ceiling Mount) - Exit

West Adjacent to C14 on opposite side of the smoke door

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:08AM

ID: 535 [↗](#)

Last Verified: 28th Mar 2024 9:09AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

6A.6 - Exit Sign Quick Fit (Ceiling Mount) - Exit

West Adjacent to C12 above outside exit door

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:06AM

ID: 531 [↗](#)

Last Verified: 28th Mar 2024 9:07AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

6A.8 - Exit Sign Quick Fit (Ceiling Mount) - Exit

West Entrance into lounge

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:04AM

ID: 522 [↗](#)

Last Verified: 28th Mar 2024 9:04AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

7B.11 - Exit Sign Quick Fit (Ceiling Mount) - Exit

West Adjacent to A8 above exit door

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:09AM

ID: 538 [↗](#)

Last Verified: 28th Mar 2024 9:10AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

7B.12 - Exit Sign Quick Fit (Ceiling Mount) - Exit

West Adjacent to A8

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:08AM

ID: 536 [↗](#)

Last Verified: 28th Mar 2024 9:09AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

7B.30 - Emergency Lighting Spitfire (Flush Mount)

West Adjacent to A7

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:08AM

ID: 534 [↗](#)

Last Verified: 28th Mar 2024 9:08AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

7B.9 - Exit Sign Quick Fit (Ceiling Mount) - Exit

West Adjacent to A16

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:10AM

ID: 540 [↗](#)

Last Verified: 28th Mar 2024 9:11AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EM 1.21 - Emergency Lighting Spitfire (Flush Mount)

East Dinning area adjacent to kitchen

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:34AM

ID: 572 [↗](#)

Last Verified: 28th Mar 2024 9:35AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

After



Click photos to enlarge

Parts/Labour

Quantity

EM 1.22 - Emergency Lighting Spitfire (Flush Mount)

East Adjacent to K8

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:35AM

ID: 574 [↗](#)

Last Verified: 28th Mar 2024 9:35AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EM G.13 - Emergency Lighting Spitfire (Flush Mount)

Adjacent to F17 east

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 12th Sep 2024 12:55PM

ID: 1592 [↗](#)

Last Verified: 12th Sep 2024 12:55PM

Description:

Emergency luminaire / exit sign not operating as required

Before

After



Click photos to enlarge


Parts/Labour

Quantity

EM G.14 - Emergency Lighting Spitfire (Flush Mount)

Adjacent to F8 east

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 12th Sep 2024 12:54PM

ID: 1591 [↗](#)

Last Verified: 12th Sep 2024 12:54PM

Description:

Emergency luminaire / exit sign not operating as required

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EM G.15 - Emergency Lighting Spitfire (Flush Mount)

East Adjacent to F7

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 12th Sep 2024 12:53PM

ID: 1588 [↗](#)

Last Verified: 12th Sep 2024 12:53PM

Description:

Emergency luminaire / exit sign not operating as required

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EM G.16 - Emergency Lighting Spitfire (Flush Mount)

Adjacent to room F18, east

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 12th Sep 2024 12:54PM

ID: 1589 [↗](#)

Last Verified: 12th Sep 2024 12:54PM

Description:

Emergency luminaire / exit sign not operating as required

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EM G.18 - Emergency Lighting Spitfire - (Surface Mount)

East Adjacent to laundry

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 12th Sep 2024 12:49PM

ID: 1586 [↗](#)

Last Verified: 12th Sep 2024 12:49PM

Description:

Emergency luminaire / exit sign not operating as required



Click photos to enlarge

Parts/Labour

Quantity

EM G.2 - Emergency Lighting Spitfire - (Surface Mount)

East adjacent to room D3

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 8:50AM

ID: 508 [↗](#)

Last Verified: 28th Mar 2024 8:51AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Location:

Adjacent to D3

Before



After



Click photos to enlarge

Parts/Labour

Quantity

EM G.25 - Emergency Lighting Spitfire - (Surface Mount)

PASS

East adjacent to room G1



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:02AM

ID: 520 [↗](#)

Last Verified: 28th Mar 2024 9:03AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before



After



Click photos to enlarge

Parts/Labour

Quantity

RESOLVED

Non-critical defect

Added: 5th Mar 2024 9:13AM

ID: 235 [↗](#)

Last Verified: 5th Mar 2024 9:13AM

Description:

Outstanding non-critical defects have not been rectified

After



Click photos to enlarge

Parts/Labour

Quantity

EM G.26 - Emergency Lighting Spitfire (Flush Mount)

PASS

Private lounge near main east entrance



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 12th Sep 2024 12:41PM

ID: 1581 [↗](#)

Last Verified: 12th Sep 2024 12:41PM

Description:

Emergency luminaire / exit sign not operating as required

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EM G.27 - Emergency Lighting Spitfire - (Surface Mount)

PASS

Private lounge near main east entrance



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 12th Sep 2024 12:41PM

ID: 1582 [↗](#)

Last Verified: 12th Sep 2024 12:42PM

Description:

Emergency luminaire / exit sign not operating as required

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EM G.28 - Emergency Lighting Spitfire - (Surface Mount)

PASS

Private lounge near main east entrance



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 12th Sep 2024 12:43PM

ID: 1583 [↗](#)

Last Verified: 12th Sep 2024 12:43PM

Description:

Emergency luminaire / exit sign not operating as required

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EM G.30 - Emergency Lighting Spitfire (Flush Mount)

East Staff room at the back of theatre seats

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:17AM

ID: 547 [↗](#)

Last Verified: 28th Mar 2024 9:17AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes



Click photos to enlarge

Parts/Labour

Quantity

EM G.31 - Emergency Lighting Spitfire (Flush Mount)

East Right of theatre seats

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 12th Sep 2024 12:45PM

ID: 1584 [↗](#)

Last Verified: 12th Sep 2024 12:45PM

Description:

Emergency luminaire / exit sign not operating as required



[Click photos to enlarge](#)

Parts/Labour

Quantity

EM G.33 - Emergency Lighting Spitfire - (Surface Mount)

PASS

East Opposite hairdresser



[Click photos to enlarge](#)

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:19AM

ID: 549 [↗](#)

Last Verified: 28th Mar 2024 9:19AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes



[Click photos to enlarge](#)

Parts/Labour

Quantity

EM G1.30 - Emergency Lighting 4FT - Single Weatherproof Batten

PASS

Adjacent to F16 east inside the stair case



[Click photos to enlarge](#)

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:25AM

ID: 555 [↗](#)

Last Verified: 28th Mar 2024 9:25AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EM G1.31 - Emergency Lighting 4FT - Single Weatherproof Batten

Adjacent to F16 east inside the stair case

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:24AM

ID: 552 [↗](#)

Last Verified: 28th Mar 2024 9:24AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EM-G.5 - Emergency Lighting Spitfire - (Surface Mount)

East reception

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 12th Sep 2024 8:06AM

ID: 1571 [↗](#)

Last Verified: 12th Sep 2024 8:06AM

Description:

Emergency luminaire / exit sign not operating as required

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EX 1.12 - Exit Sign Quick Fit (Ceiling Mount) - Exit

East Adjacent to L14 in front of fire door

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:31AM

ID: 565 [↗](#)

Last Verified: 28th Mar 2024 9:31AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EX 1.13 - Exit Sign Quick Fit (Ceiling Mount) - Exit

East Adjacent to L14

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:31AM

ID: 564 [↗](#)

Last Verified: 28th Mar 2024 9:31AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge


Parts/Labour

Quantity

EX 1.17 - Exit Sign Pyramid (Ceiling Mount) - Exit

East North end of L block

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:27AM

ID: 558 [↗](#)

Last Verified: 28th Mar 2024 9:27AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EX 1.18 - Exit Sign Pyramid (Ceiling Mount) - Exit

East North end of L block above fire door

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:29AM

ID: 560 [↗](#)

Last Verified: 28th Mar 2024 9:29AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EX 1.26 - Exit Sign Quick Fit (Ceiling Mount) - Exit

Adjacent to F16 east inside the stair case

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:24AM

ID: 553 [↗](#)

Last Verified: 28th Mar 2024 9:25AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EX 1.5 - Exit Sign Quick Fit (Ceiling Mount) - Exit

East Adjacent to K2

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:42AM

ID: 584 [↗](#)

Last Verified: 28th Mar 2024 9:42AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

After



Click photos to enlarge

Parts/Labour

Quantity

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:42AM

ID: 583 [↗](#)

Last Verified: 28th Mar 2024 9:42AM

Description:

Emergency luminaire / exit sign not operating as required

After



Click photos to enlarge

Parts/Labour

Quantity

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:42AM

ID: 582 [↗](#)

Last Verified: 28th Mar 2024 9:42AM

Description:

Emergency luminaire / exit sign is damage / deteriorated that is adversely affect its function

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EX 1.8 - Exit Sign Quick Fit (Ceiling Mount) - Exit

East Adjacent to J3

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:40AM

ID: 580 [↗](#)

Last Verified: 28th Mar 2024 9:40AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

After



Click photos to enlarge

Parts/Labour

Quantity

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:40AM

ID: 581 [↗](#)

Last Verified: 28th Mar 2024 9:40AM

Description:

Emergency luminaire / exit sign not operating as required

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EX G.10A - Exit Sign Quick Fit (Ceiling Mount) - Exit

PASS

Opposite H11 east



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 8:55AM

ID: 516 [↗](#)

Last Verified: 28th Mar 2024 8:55AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EX G.2 - Exit Sign Quick Fit (Ceiling Mount) - Exit
Adjacent to room D7(east)

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 8:53AM

ID: 514 [↗](#)

Last Verified: 28th Mar 2024 8:54AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before



After



Click photos to enlarge

Parts/Labour

Quantity

RESOLVED

Non-critical defect

Added: 28th Mar 2024 8:53AM

ID: 513 [↗](#)

Last Verified: 28th Mar 2024 8:54AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Location:

Adjacent to D7



Click photos to enlarge

Parts/Labour

Quantity

EX G.20 - Exit Sign Jumbo (Ceiling Mount) - Exit
East Adjacent to room F18

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:22AM

ID: 550 [↗](#)

Last Verified: 28th Mar 2024 9:22AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EX G.9 - Exit Sign Quick Fit (Ceiling Mount) - Exit
Adjacent to H3 east

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 8:56AM

ID: 517 [↗](#)

Last Verified: 28th Mar 2024 8:57AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

EX1.19 - Exit Sign Quick Fit (Ceiling Mount) - Exit
North east fire stairs

PASS



Click photos to enlarge

RESOLVED

Non-critical defect

Added: 28th Mar 2024 9:28AM

ID: 559 [↗](#)

Last Verified: 28th Mar 2024 9:28AM

Description:

Emergency luminaire or exit sign did not meet the in-service duration of 90 minutes

Before

After



Click photos to enlarge

Parts/Labour

Quantity

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician

Date/Time

Accreditations

Signature

Micra Service
Technician

12th Sep 2024
3:06PM

Mike Alford

12th Sep 2024
3:06PM

Company Accreditations: