

SERVICE REPORT

<p>Heritage Aged Care - Twin Parks Reservoir</p> <p>33 Blake Street Reservoir Victoria 3073</p>	<p>Report Number R-00780</p> <p>Reference</p> <p>Service Date: 12th September 2024</p>
-----------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

Scope of Works
10 - Portable and Wheeled Fire Extinguishers (2012): Six-monthly (23)

0	Critical Defects	A defect that renders a system inoperative.
0	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.
230	Passed Assets	

Servicing Summary		
Service	Asset	Quantity
10 - Portable and Wheeled Fire Extinguishers (2012): Six-monthly	10 - Fire Extinguishers - Portable	23

Maintenance

10 - Portable and Wheeled Fire Extinguishers (2012): Six-monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset	Status
-------	--------

E G.10 - Fire Extinguisher DCP AB(E) 2.5KG	East Bbq area	PASS
-------------------------------------------------------	---------------	-------------



W G.7 - Fire Extinguisher DCP AB(E) 1.5KG	Outside near nurse station	PASS
------------------------------------------------------	----------------------------	-------------



W G.6 - Fire Extinguisher DCP AB(E) 1.5KG	Adjacent to A9	PASS
------------------------------------------------------	----------------	-------------



W G.5 - Fire Extinguisher DCP AB(E) 1.5KG	Laundry	PASS
------------------------------------------------------	---------	-------------



W G.4 - Fire Extinguisher DCP AB(E) 4.5KG	In staff room upstairs	PASS
------------------------------------------------------	------------------------	-------------



W G.3 - Fire Extinguisher DCP AB(E) 1.5KG	Kitchen office west	PASS
------------------------------------------------------	---------------------	-------------



Asset		Status
W G.2 - Fire Extinguisher DCP AB(E) 1.5KG	Kitchen West	<div data-bbox="1406 293 1490 327" style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</div>
		
W G.1 - Fire Extinguisher DCP AB(E) 1.5KG	Adjacent to C11	<div data-bbox="1406 555 1490 589" style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</div>
		
1.6 - Fire Extinguisher Wet Chemical 7.0Lt	Kitchen	<div data-bbox="1406 817 1490 851" style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</div>
		
1.5 - Fire Extinguisher DCP AB(E) 2.5KG	Kitchen	<div data-bbox="1406 1079 1490 1113" style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</div>
		
1.4 - Fire Extinguisher Air/Water 9.0LT	Next to staff toilet	<div data-bbox="1406 1341 1490 1375" style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</div>
		
1.3 - Fire Extinguisher DCP AB(E) 2.5KG	Opposite to Infection control trolley and control kits room	<div data-bbox="1406 1603 1490 1637" style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</div>
		
E 1.2 - Fire Extinguisher Air/Water 9.0LT	Doors into library from J corridor	<div data-bbox="1406 1865 1490 1899" style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</div>
		

Asset		Status
E 1.1 - Fire Extinguisher DCP AB(E) 2.5KG	Adjacent of the elevator in J corridor	PASS
		
E G.9 - Fire Extinguisher DCP AB(E) 2.5KG	Laundry	PASS
		
E G.8 - Fire Extinguisher DCP AB(E) 4.5KG	Adjacent to doctors room east ground	PASS
		
E G.7 - Fire Extinguisher DCP AB(E) 2.5KG	Adjacent to F8 east	PASS
		
E G.6 - Fire Extinguisher DCP AB(E) 2.5KG	Laundry	PASS
		
E G.5 - Fire Extinguisher DCP AB(E) 2.5KG	Opposite laundry	PASS
		
E G.4 - Fire Extinguisher DCP AB(E) 2.5KG	Kitchen	PASS

Asset	Status
	
E G.3 - Fire Extinguisher Air/Water 9.0LT	Kitchen
PASS	
	
E G.2 - Fire Extinguisher DCP AB(E) 2.5KG	Reception elevator east
PASS	
	
E G.1 - Fire Extinguisher Air/Water 9.0LT	East reception
PASS	
	

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Service Technician	12th Sep 2024 3:06PM		
Mike Alford	12th Sep 2024 3:06PM		

Company Accreditations: