

SERVICE REPORT

Australian Unity - Walmsley Community Centre

Greeves Drive
Kilsyth
Victoria 3137

Report Number R-02113
Reference WALMSLY-2401744
Service Date:

Scope of Works

Path of Travel & Discharge to Exit (2012): Quarterly (6)

0	Critical Defects	A defect that renders a system inoperative.
0	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.
6	Passed Assets	

Servicing Summary

Service	Asset	Quantity
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	6

Maintenance

Path of Travel & Discharge to Exit (2012): Quarterly

Asset	Status
007 - Path of Travel & Discharge to Exit Discharge from Exit	North East
	PASS

Asset		Status
		
006 - Path of Travel & Discharge to Exit Discharge from Exit	Front entrance	PASS
		
004 - Path of Travel & Discharge to Exit Exit Door	North East	PASS
		
003 - Path of Travel & Discharge to Exit Path of Travel	Entrance, North East & Rear Kitchen	PASS
		
002 - Path of Travel & Discharge to Exit Exit Door	Entrance, North East & Rear Kitchen	PASS
		
001 - Path of Travel & Discharge to Exit Exit Door	Entrance	PASS
		

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Service Technician	None		

Company Accreditations: