

## SERVICE REPORT

<b>Heritage Aged Care - Twin Parks Reservoir</b>	<b>Report Number R-00409</b>
<b>33 Blake Street</b>	<b>Reference</b>
<b>Reservoir</b>	<b>Service Date:</b>
<b>Victoria 3073</b>	

<b>Scope of Works</b>
Path of Travel & Discharge to Exit (2012): Quarterly (28)

<b>0 Critical Defects</b>	A defect that renders a system inoperative.
<b>3 Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>6 Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0 Recommendations</b>	A modification suggested to improve the system performance.
<b>0 Informational Notes</b>	Detailed advice or general comment.

<b>Servicing Summary</b>		
<b>Service</b>	<b>Asset</b>	<b>Quantity</b>
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	28

## Maintenance

<b>Path of Travel &amp; Discharge to Exit (2012): Quarterly</b>		
<b>Asset</b>		<b>Status</b>
055 - Path of Travel & Discharge to Exit Fire Isolated Stairs	1st floor east	<b>PASS</b>

Asset		Status
054 - Path of Travel & Discharge to Exit Fire Isolated Stairs	1st floor east	PASS
053 - Path of Travel & Discharge to Exit Fire Isolated Stairs	1st floor east	PASS
052 - Path of Travel & Discharge to Exit Fire Isolated Stairs	1st floor east	PASS
051 - Path of Travel & Discharge to Exit Path of Travel	1st floor staff room	FAIL

**Non-conformance**

ID: 649 [↗](#)

Added: 2nd Apr 2024 7:58AM

Last Verified: 2nd Apr 2024 8:38AM

**Description:**

Stairs require installation of anti slip stair nosing to ensure safe egress

**Resolution:**

**Location:**

1st floor staff room



Click photos to enlarge

W G.7 - Path of Travel & Discharge to Exit Exit Door	West Kitchen	PASS
W G.6 - Path of Travel & Discharge to Exit Exit Door	West exit door adjacent to C12	PASS
W G.5 - Path of Travel & Discharge to Exit Exit Door	West south lounge	FAIL

Asset	Status
<div style="display: flex; justify-content: space-between;"> <span data-bbox="122 288 339 315"><b>Non-critical defect</b></span> <span data-bbox="1157 288 1490 315">Added: 28th Mar 2024 3:14PM</span> </div> <div style="display: flex; justify-content: space-between;"> <span data-bbox="122 327 228 353">ID: 633 <a href="#">↗</a></span> <span data-bbox="1096 327 1490 353">Last Verified: 28th Mar 2024 3:15PM</span> </div> <p data-bbox="122 392 264 418"><b>Description:</b> Egress doors won't open during fire alarm Door damaged, mag release ok.</p> <p data-bbox="122 512 255 539"><b>Resolution:</b></p> <p data-bbox="122 551 231 577"><b>Location:</b> West south lounge</p> <p data-bbox="122 633 405 660"><b>Quote:</b> <span style="background-color: #FFD700; padding: 2px;">SUBMITTED</span> <a href="#">↗</a></p> <div data-bbox="122 698 225 801">  </div> <p data-bbox="122 808 323 835">Click photos to enlarge</p>	
<b>W G.4 - Path of Travel &amp; Discharge to Exit Exit Door</b>	West exit door adjacent to A7 <span style="float: right; background-color: #28a745; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
<b>W G.3 - Path of Travel &amp; Discharge to Exit Exit Door</b>	West exit door in laundry <span style="float: right; background-color: #28a745; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
<b>W G.2 - Path of Travel &amp; Discharge to Exit Exit Door</b>	West exit gate in the courtyard <span style="float: right; background-color: #28a745; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
<div style="display: flex; justify-content: space-between;"> <span data-bbox="122 1211 339 1238"><b>Non-critical defect</b></span> <span data-bbox="1157 1211 1490 1238">Added: 28th Mar 2024 3:09PM</span> </div> <div style="display: flex; justify-content: space-between;"> <span data-bbox="122 1249 228 1276">ID: 629 <a href="#">↗</a></span> <span data-bbox="1096 1249 1490 1276">Last Verified: 28th Mar 2024 3:12PM</span> </div> <p data-bbox="122 1314 663 1377"><b>Description:</b> Not opening on active fire alarm for path of egress</p> <p data-bbox="122 1400 255 1426"><b>Resolution:</b></p> <p data-bbox="122 1438 474 1500"><b>Location:</b> Main gate to west front entrance</p> <p data-bbox="122 1518 405 1545"><b>Quote:</b> <span style="background-color: #FFD700; padding: 2px;">SUBMITTED</span> <a href="#">↗</a></p> <div data-bbox="122 1585 225 1688">  </div> <p data-bbox="122 1695 323 1722">Click photos to enlarge</p>	
<b>W G.1 - Path of Travel &amp; Discharge to Exit Exit Door</b>	West exit door near nurse station <span style="float: right; background-color: #28a745; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
<b>E G.16 - Path of Travel &amp; Discharge to Exit Exit Door</b>	East kitchen storage room <span style="float: right; background-color: #28a745; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
<b>E G.15 - Path of Travel &amp; Discharge to Exit Exit Door</b>	East exit door to carpark <span style="float: right; background-color: #28a745; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>

Asset	Status
<b>E G.13 - Path of Travel &amp; Discharge to Exit Exit Door</b> East theatre exit door left	<span style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
<b>E G.14 - Path of Travel &amp; Discharge to Exit Exit Door</b> East fire exit door adjacent to theatre courtyard	<span style="background-color: red; color: white; padding: 2px 5px; border-radius: 3px;">FAIL</span>
<div style="display: flex; justify-content: space-between;"> <div data-bbox="119 515 335 582"> <p><b>Non-conformance</b> ID: 988 <a href="#">↗</a></p> </div> <div data-bbox="1093 515 1492 582"> <p>Added: 17th Jun 2024 7:39AM Last Verified: 17th Jun 2024 7:39AM</p> </div> </div> <p data-bbox="119 616 327 683"><b>Description:</b> Non-Conformance</p> <p data-bbox="119 705 255 728"><b>Resolution:</b></p> <div data-bbox="119 739 223 840">  </div> <p data-bbox="119 851 327 873">Click photos to enlarge</p>	
<div style="display: flex; justify-content: space-between;"> <div data-bbox="119 907 335 974"> <p><b>Non-conformance</b> ID: 604 <a href="#">↗</a></p> </div> <div data-bbox="1093 907 1492 974"> <p>Added: 28th Mar 2024 1:10PM Last Verified: 28th Mar 2024 1:12PM</p> </div> </div> <p data-bbox="119 1008 351 1075"><b>Description:</b> Combustible material</p> <p data-bbox="119 1097 255 1120"><b>Resolution:</b></p> <p data-bbox="119 1131 231 1153"><b>Location:</b> East fire exit door adjacent to theatre courtyard</p> <div data-bbox="119 1220 223 1321">  </div> <p data-bbox="119 1332 327 1355">Click photos to enlarge</p>	
<b>E G.12 - Path of Travel &amp; Discharge to Exit Exit Door</b> East theatre exit door right	<span style="background-color: red; color: white; padding: 2px 5px; border-radius: 3px;">FAIL</span>
<div style="display: flex; justify-content: space-between;"> <div data-bbox="119 1500 343 1568"> <p><b>Non-critical defect</b> ID: 987 <a href="#">↗</a></p> </div> <div data-bbox="1093 1500 1492 1568"> <p>Added: 17th Jun 2024 7:34AM Last Verified: 17th Jun 2024 7:35AM</p> </div> </div> <p data-bbox="119 1601 327 1668"><b>Description:</b> Non-Critical Defect</p> <p data-bbox="119 1691 255 1713"><b>Resolution:</b></p> <p data-bbox="119 1724 231 1747"><b>Location:</b> EG 12</p> <div data-bbox="119 1814 223 1915">  </div> <p data-bbox="119 1926 327 1948">Click photos to enlarge</p>	
<b>E G.11 - Path of Travel &amp; Discharge to Exit Exit Door</b> East exit gate onto blake street	<span style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>

Asset		Status
E G.10 - Path of Travel & Discharge to Exit Exit Door	East ground exit doors adjacent to Laundry	PASS
E G.9 - Path of Travel & Discharge to Exit Exit Door	East exit doors adjacent to room F18	PASS
E G.8 - Path of Travel & Discharge to Exit Exit Door	East fire stairs adjacent to room F16	PASS
E G.7 - Path of Travel & Discharge to Exit Exit Door	East exit gate onto davis street	PASS
E G.6 - Path of Travel & Discharge to Exit Exit Door	East exit doors adjacent to room F15	PASS
E G.5 - Path of Travel & Discharge to Exit Exit Door	East exit doors adjacent to room E3	PASS
E G.4 - Path of Travel & Discharge to Exit Exit Door	East exit doors adjacent to room D6	PASS
E G.3 - Path of Travel & Discharge to Exit Exit Door	East fire stairs adjacent to room D4	PASS
E G.2 - Path of Travel & Discharge to Exit Exit Door	East ground reception fire stairs	FAIL
<div style="background-color: #fff9c4; padding: 10px;"> <p><b>Non-conformance</b> <span style="float: right;">Added: 28th Mar 2024 12:41PM</span></p> <p>ID: 601 <a href="#">↗</a> <span style="float: right;">Last Verified: 28th Mar 2024 12:43PM</span></p> <p><b>Description:</b> Combustible material under the stair well. NBN cabinet shouldn't be located in stairwell.</p> <p><b>Resolution:</b></p> <p><b>Location:</b> East ground reception fire stairs</p> <div style="display: flex; align-items: center;">  </div> <p><a href="#">Click photos to enlarge</a></p> </div>		
E G.1 - Path of Travel & Discharge to Exit Automatic Doors	East main entrance	PASS

## Repairs

### E G.3 - Path of Travel & Discharge to Exit Exit Door

PASS

East fire stairs adjacent to room D4

**RESOLVED** Non-conformance

Added: 28th Mar 2024 12:45PM

ID: 602 [↗](#)

Last Verified: 28th Mar 2024 12:46PM

#### Description:

Combustible materials under stairwell.

#### Location:

East fire stairs adjacent to room D4

#### Before



#### After



Click photos to enlarge

#### Parts/Labour

#### Quantity

### E G.8 - Path of Travel & Discharge to Exit Exit Door

PASS

East fire stairs adjacent to room F16

**RESOLVED** Non-conformance

Added: 28th Mar 2024 12:57PM

ID: 603 [↗](#)

Last Verified: 28th Mar 2024 12:58PM

#### Description:

Combustible material under stairwell

#### Location:

East fire stairs adjacent to room F16

#### Before



#### After



Click photos to enlarge

#### Parts/Labour

#### Quantity

## Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

#### Technician

#### Date/Time

#### Accreditations

#### Signature

Micra Air  
Technician

None

**Company Accreditations:**