

SERVICE REPORT

Sacred Heart Girls College 113 Warrigal Road Oakleigh Victoria 3166	Report Number R-00364 Reference Service Date: 6th May 2024
--	---

Scope of Works 06 - Fire Detection Systems - FIP (2012): Monthly (4)
--

0	Critical Defects	A defect that renders a system inoperative.
5	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
3	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
1	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.

Servicing Summary		
Service	Asset	Quantity
06 - Fire Detection Systems - FIP (2012): Monthly	06 - Fire Detection Systems - Panels	4

Maintenance

06 - Fire Detection Systems - FIP (2012): Monthly AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset	Status
005 - Fire Detection Panel Vigilant MX1 Entry fitness building	PASS

Asset	Status
<p>Non-critical defect ID: 768 ↗</p> <p>Description: Common/general visual/audible indications do not operate</p> <p>Resolution: Technician to investigate cause of issue and rectify where possible (excluding parts)</p> <p>Location: FIP</p>	<p>Added: 10th Apr 2024 12:18PM Last Verified: 10th Apr 2024 12:18PM</p>
<p>004 - Fire Detection Panel Vigilant MX1 D Block ground floor PASS</p>	
<p>Non-critical defect ID: 767 ↗</p> <p>Description: Common/general visual/audible indications do not operate</p> <p>Resolution: Technician to investigate cause of issue and rectify where possible (excluding parts)</p> <p>Location: FIP</p>	<p>Added: 10th Apr 2024 12:17PM Last Verified: 10th Apr 2024 12:18PM</p>
<p>Non-conformance ID: 43 ↗</p> <p>Description: No zone block plans</p> <p>Resolution: create new zone block plans</p> <p>Location: D Block FIP</p> <p>Quote: EXPIRED ↗</p>	<p>Added: 9th Jul 2023 6:31PM Last Verified: 9th Jul 2023 6:36PM</p>
<p>003 - Fire Detection Panel Vigilant MX1 Main Entrance C Block PASS</p>	
<p>Non-critical defect ID: 766 ↗</p> <p>Description: Common/general visual/audible indications do not operate</p> <p>Resolution: Technician to investigate cause of issue and rectify where possible (excluding parts)</p> <p>Location: FIP</p>	<p>Added: 10th Apr 2024 12:17PM Last Verified: 10th Apr 2024 12:17PM</p>

Asset	Status
<p>Non-conformance ID: 36 ↗</p> <p>Description: Supplementary drawings not legible</p> <p>Resolution: Supply and install new block plan</p> <p>Location: Main FIP</p>	<p>Added: 9th Jul 2023 5:19PM Last Verified: 9th Jul 2023 6:05PM</p>
<p>002 - Fire Detection Panel Vigilant MX1 Fourviere Ground floor PASS</p>	
<p>Non-critical defect ID: 765 ↗</p> <p>Description: Common/general visual/audible indications do not operate</p> <p>Resolution: Technician to investigate cause of issue and rectify where possible (excluding parts)</p> <p>Location: FIP</p>	<p>Added: 10th Apr 2024 12:16PM Last Verified: 10th Apr 2024 12:17PM</p>
<p>Non-critical defect ID: 40 ↗</p> <p>Description: All remote indicators didn't operate</p> <p>Resolution: Investigate and rectify if possible all remote indicators</p> <p>Location: Fourviere remote indicators</p>	<p>Added: 9th Jul 2023 6:23PM Last Verified: 9th Jul 2023 6:29PM</p>
<p>Non-conformance ID: 42 ↗</p> <p>Description: No zone block plans</p> <p>Resolution: Test and produce new zone block plans</p> <p>Location: Fourviere</p> <p>Quote: EXPIRED ↗</p>	<p>Added: 9th Jul 2023 6:19PM Last Verified: 9th Jul 2023 6:29PM</p>

Asset**Status****Recommendation**ID: 41 [↗](#)

Added: 9th Jul 2023 6:25PM

Last Verified: 9th Jul 2023 6:29PM

Description:

Plans for Detector numbers and location not readable

Resolution:

100% to create new plans with latest layout

Location:

Fourviere

Logbooks**Sub FIP** [↗](#)

Classic Logbook

**D Block** [↗](#)

Classic Logbook

**Fourviere** [↗](#)

Classic Logbook

**EWIS** [↗](#)

Classic Logbook

**Main FIP** [↗](#)

Classic Logbook

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician**Date/Time****Accreditations****Signature**Micra Fire
Technician6th May 2024
8:33AM

Mike Alford

6th May 2024
8:33AM

Signatures

A handwritten signature in black ink, appearing to be 'Denim', is centered within a white rectangular box. The box is surrounded by a dashed black border.

Denim

Company Accreditations: