

## SERVICE REPORT

<p><b>Australian Unity - Walmsley Community Centre</b></p> <p>Greeves Drive        Kilsyth        Victoria 3137</p>	<p><b>Report Number R-00636</b></p> <p><b>Reference WALMSLY-2401175</b></p> <p><b>Service Date: 23rd August 2024</b></p>
---	--

### Scope of Works

Path of Travel & Discharge to Exit (2012): Quarterly (5)

<b>0 Critical Defects</b>	A defect that renders a system inoperative.
<b>0 Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>0 Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0 Recommendations</b>	A modification suggested to improve the system performance.
<b>0 Informational Notes</b>	Detailed advice or general comment.
<b>14 Passed Assets</b>	

### Servicing Summary

Service	Asset	Quantity
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	6

### Maintenance

#### Path of Travel & Discharge to Exit (2012): Quarterly

Asset	Status
007 - Path of Travel & Discharge to Exit Discharge from Exit	North East <span style="float: right; background-color: #27ae60; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>

Asset		Status
		
<b>006 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	Front entrance	<span style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
		
<b>004 - Path of Travel &amp; Discharge to Exit Exit Door</b>	North East	<span style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
		
<b>003 - Path of Travel &amp; Discharge to Exit Path of Travel</b>	Entrance, North East & Rear Kitchen	<span style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
		
<b>002 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Entrance, North East & Rear Kitchen	<span style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
		
<b>001 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Entrance	<span style="background-color: green; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>
		

## Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Mike Alford	23rd Aug 2024 12AM		

## Company Accreditations: