

SERVICE REPORT

Australian Unity - Victoria Grange Aged Care (AC)
 502 Burwood Hwy,
 Vermont South VIC 3133

Report Number R-01048
Reference VICGR-AC2401751
Service Date: 4th October 2024

Scope of Works

Fire Pumpsets - (Diesel and Electric) (2012): Monthly (1)

0	Critical Defects	A defect that renders a system inoperative.
0	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.
1	Passed Assets	

Servicing Summary

Service	Asset	Quantity
03 - Fire Pumpsets - (Diesel and Electric) (2012): Monthly	03 - Fire Pump - Diesel	1

Maintenance

03 - Fire Pumpsets - (Diesel and Electric) (2012): Monthly

AS1851-2012 (a1) - Routine service of fire protection systems and equipment

Asset

Status

001 - Fire Pump - Diesel Diesel -
Hydrant System Pump

Pump shed on driveway

PASS

Photos



Click photos to enlarge

Logbooks



03 - Fire pumpsets [↗](#)

Classic Logbook



02 - Automatic fire sprinkler systems [↗](#)

Classic Logbook

Signoff

Maintenance has been carried out in accordance with current regulations.

Technician

Date/Time

Accreditations


Signature

Mike Alford

4th Oct 2024

11:25AM

Signatures

A handwritten signature consisting of a large, stylized loop followed by a horizontal line extending to the right. The signature is enclosed in a dashed rectangular box.

Js

Company Accreditations: