

## SERVICE REPORT

<p><b>Australian Unity - Peninsula Grange</b></p> <p><b>431 Racecourse Road</b>  <b>Mornington</b>  <b>Victoria 3931</b></p>	<p><b>Report Number R-00234</b>  <b>Reference PENG-RC-2400234</b>  <b>Service Date:</b></p>
--	---

<b>Scope of Works</b>
Path of Travel & Discharge to Exit (2012): Annual (0)

<b>0 Critical Defects</b>	A defect that renders a system inoperative.
<b>0 Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>0 Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0 Recommendations</b>	A modification suggested to improve the system performance.
<b>0 Informational Notes</b>	Detailed advice or general comment.

<b>Servicing Summary</b>		
<b>Service</b>	<b>Asset</b>	<b>Quantity</b>
Path of Travel & Discharge to Exit (2012): Annual	12 - Path of Travel & Discharge to Exit	18

## Maintenance

<b>Path of Travel &amp; Discharge to Exit (2012): Annual</b>		
<b>Asset</b>		<b>Status</b>
4 - Path of Travel & Discharge to Exit Exit Door	Multi purpose room 1 west	<span style="background-color: #27ae60; color: white; padding: 2px 5px; border-radius: 3px;">PASS</span>

Asset		Status
13 - Path of Travel & Discharge to Exit Exit Door	Work shop west	PASS
14 - Path of Travel & Discharge to Exit Exit Door	East Adjacent to managers office	PASS
11 - Path of Travel & Discharge to Exit Exit Door	West lounge	PASS
17 - Path of Travel & Discharge to Exit Exit Door	East Pool room north exit door	PASS
9 - Path of Travel & Discharge to Exit Exit Door	Switch room west	PASS
6 - Path of Travel & Discharge to Exit Exit Door	Multi purpose room 3 west	PASS
12 - Path of Travel & Discharge to Exit Exit Door	West lounge	PASS
15 - Path of Travel & Discharge to Exit Exit Door	East Meeting room	PASS
18 - Path of Travel & Discharge to Exit Exit Door	Pool plant room east	PASS
1 - Path of Travel & Discharge to Exit Automatic Doors	West Main Entrance doors	PASS
10 - Path of Travel & Discharge to Exit Exit Door	West lounge	PASS
7 - Path of Travel & Discharge to Exit Exit Door	West lounge	PASS
16 - Path of Travel & Discharge to Exit Exit Door	East Pool room north exit door	PASS
2 - Path of Travel & Discharge to Exit Automatic Doors	West Main Entrance doors second one	PASS
5 - Path of Travel & Discharge to Exit Exit Door	Multi purpose room 2 west	PASS

Asset		Status
8 - Path of Travel & Discharge to Exit Exit Door	Adjacent to store room west	PASS
3 - Path of Travel & Discharge to Exit Automatic Doors	North exit doors near reception	PASS

**Signoff**

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Fire Technician	None		
Mike Alford	None		

**Company Accreditations:**