

## SERVICE REPORT


<p><b>Australian Unity - Peninsula Grange</b></p> <p>431 Racecourse Road        Mornington        Victoria 3931</p>	<p><b>Report Number R-00606</b></p> <p><b>Reference PENG-RC-2401523</b></p> <p><b>Service Date: 19th August 2024</b></p>
---	--

<b>Scope of Works</b>
Path of Travel & Discharge to Exit (2012): Quarterly (19)

<b>0 Critical Defects</b>	A defect that renders a system inoperative.
<b>0 Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>2 Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0 Recommendations</b>	A modification suggested to improve the system performance.
<b>0 Informational Notes</b>	Detailed advice or general comment.
<b>48 Passed Assets</b>	

<b>Servicing Summary</b>		
<b>Service</b>	<b>Asset</b>	<b>Quantity</b>
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	39

<b>Maintenance</b>		
<b>Path of Travel &amp; Discharge to Exit (2012): Quarterly</b>		
<b>Asset</b>		<b>Status</b>
048 - Path of Travel & Discharge to Exit Path of Travel	Adjacent to kitchen	<span style="background-color: #27ae60; color: white; padding: 2px 5px;">PASS</span>

Asset	Status
	
<b>047 - Path of Travel &amp; Discharge to Exit Path of Travel</b>	Adjacent to craft room <span style="float: right;"><b>PASS</b></span>
	
<b>046 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	Workshop exit <span style="float: right;"><b>PASS</b></span>
	
<b>045 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	South corridor <span style="float: right;"><b>PASS</b></span>
	
<b>044 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	South entrance <span style="float: right;"><b>PASS</b></span>
	
<b>043 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Pool <span style="float: right;"><b>PASS</b></span>
	
<b>042 - Path of Travel &amp; Discharge to Exit Path of Travel</b>	Pool <span style="float: right;"><b>PASS</b></span>
	

Asset		Status
041 - Path of Travel & Discharge to Exit Discharge from Exit	North pool exit	PASS
		
040 - Path of Travel & Discharge to Exit Discharge from Exit	North pool exit	PASS
		
039 - Path of Travel & Discharge to Exit Path of Travel	Admin office corridor	PASS
		
038 - Path of Travel & Discharge to Exit Discharge from Exit	Admin office exit	PASS
		
037 - Path of Travel & Discharge to Exit Discharge from Exit	East exit	PASS
		
036 - Path of Travel & Discharge to Exit Discharge from Exit	North entrance	PASS
		
035 - Path of Travel & Discharge to Exit Discharge from Exit	Multi purpose room 1	PASS

Asset	Status
	
<b>034 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	Multi purpose room 1 <span style="float: right;"><b>PASS</b></span>
	
<b>033 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	Multi purpose room 3 <span style="float: right;"><b>PASS</b></span>
	
<b>032 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	North dining <span style="float: right;"><b>PASS</b></span>
	
<b>031 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	North dining <span style="float: right;"><b>PASS</b></span>
	
<b>030 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	West dining <span style="float: right;"><b>PASS</b></span>
	
<b>029 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	West dining <span style="float: right;"><b>PASS</b></span>
	

Asset		Status
025 - Path of Travel & Discharge to Exit Exit Door	North exit	PASS
		
18 - Path of Travel & Discharge to Exit Exit Door	Pool plant room east	PASS
17 - Path of Travel & Discharge to Exit Exit Door	East Pool room north exit door	PASS
		
16 - Path of Travel & Discharge to Exit Exit Door	East Pool room north exit door	PASS
		
15 - Path of Travel & Discharge to Exit Exit Door	East Meeting room	PASS
		
14 - Path of Travel & Discharge to Exit Exit Door	East Adjacent to managers office	PASS
		
13 - Path of Travel & Discharge to Exit Exit Door	Work shop west	PASS
		
12 - Path of Travel & Discharge to Exit Exit Door	West lounge	PASS

Asset		Status
		
<b>11 - Path of Travel &amp; Discharge to Exit Exit Door</b>	West lounge	<b>PASS</b>
		
<b>10 - Path of Travel &amp; Discharge to Exit Exit Door</b>	West lounge	<b>PASS</b>
		
<b>9 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Switch room west	<b>PASS</b>
<b>8 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Adjacent to store room west	<b>PASS</b>
		
<b>7 - Path of Travel &amp; Discharge to Exit Exit Door</b>	West lounge	<b>PASS</b>
		
<b>6 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Multi purpose room 3 west	<b>PASS</b>
		
<b>5 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Multi purpose room 2 west	<b>PASS</b>

Asset		Status
		
<b>4 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Multi purpose room 1 west	<b>PASS</b>
		
<b>3 - Path of Travel &amp; Discharge to Exit Automatic Doors</b>	North exit doors near reception	<b>PASS</b>
		
<b>2 - Path of Travel &amp; Discharge to Exit Automatic Doors</b>	West Main Entrance doors second one	<b>FAIL</b>
		
<div style="background-color: #fff9c4; padding: 5px;"> <p><b>Non-conformance</b> <span style="float: right;">Added: 13th Jun 2024 12:06PM</span>  ID: 981 <a href="#">↗</a> <span style="float: right;">Last Verified: 13th Jun 2024 12:07PM</span></p> </div>		
<div style="background-color: #fff9c4; padding: 5px;"> <p><b>Description:</b> Non-Conformance</p> <p><b>Resolution:</b></p> <div style="display: flex; align-items: center;">  </div> <p><a href="#">Click photos to enlarge</a></p> </div>		
<div style="background-color: #fff9c4; padding: 5px;"> <p><b>Non-conformance</b> <span style="float: right;">Added: 13th Jun 2024 12:06PM</span>  ID: 980 <a href="#">↗</a> <span style="float: right;">Last Verified: 13th Jun 2024 12:07PM</span></p> </div>		
<div style="background-color: #fff9c4; padding: 5px;"> <p><b>Description:</b> Non-Conformance</p> <p><b>Resolution:</b></p> </div>		
<b>1 - Path of Travel &amp; Discharge to Exit Automatic Doors</b>	West Main Entrance doors	<b>PASS</b>

<b>Asset</b>	<b>Status</b>
--------------	---------------



**Logbooks**



**06 - Fire Detection Systems** [↗](#)  
Classic Logbook

**Signoff**

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

<b>Technician</b>	<b>Date/Time</b>	<b>Accreditations</b>	<b>Signature</b>
Mike Alford	19th Aug 2024 12AM		

**Company Accreditations:**