

## SERVICE REPORT

**Australian Unity - Victoria Grange Aged Care (AC)**  
 502 Burwood Hwy,  
 Vermont South VIC 3133

**Report Number R-00827**  
**Reference VICGR-AC2401518**  
**Service Date: 9th September 2024**

### Scope of Works

Path of Travel & Discharge to Exit (2012): Quarterly (22)

0	<b>Critical Defects</b>	A defect that renders a system inoperative.
0	<b>Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
0	<b>Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
0	<b>Recommendations</b>	A modification suggested to improve the system performance.
0	<b>Informational Notes</b>	Detailed advice or general comment.
98	<b>Passed Assets</b>	

### Servicing Summary

Service	Asset	Quantity
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	33


### Maintenance

#### Path of Travel & Discharge to Exit (2012): Quarterly

Asset	Status
061 - Path of Travel & Discharge to Exit Exit Door Kitchen	<b>PASS</b>

Asset	Status
	
<b>062 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	<b>PASS</b>
	
<b>056 - Path of Travel &amp; Discharge to Exit Path of Travel</b>	<b>PASS</b>
	
<b>053 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	<b>PASS</b>
	
<b>052 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	<b>PASS</b>
	
<b>058 - Path of Travel &amp; Discharge to Exit Exit Door</b>	<b>PASS</b>
	
<b>060 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	<b>PASS</b>
	

Asset		Status
059 - Path of Travel & Discharge to Exit Exit Door	Level 2 north exit gate	PASS
		
055 - Path of Travel & Discharge to Exit Discharge from Exit	Level 1 south exit	PASS
		
054 - Path of Travel & Discharge to Exit Discharge from Exit	Level 2 North stairwell	PASS
		
057 - Path of Travel & Discharge to Exit Path of Travel	Level 3 stairs	PASS
		
051 - Path of Travel & Discharge to Exit Path of Travel	Aged Care Level 3 South Orchard Stairwell	PASS
		
050 - Path of Travel & Discharge to Exit Exit Door	Aged Care Level 3 South Orchard	PASS
		
049 - Path of Travel & Discharge to Exit Path of Travel	Aged Care Level 3 South Orchard	PASS

Asset	Status
	
<b>048 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	Aged Care Level 3 Exits
	<b>PASS</b>
<b>047 - Path of Travel &amp; Discharge to Exit Path of Travel</b>	Aged Care Level 3 North Orchard Stairwell
	<b>PASS</b>
	
<b>046 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Aged Care Level 3 North Orchard
	<b>PASS</b>
<b>045 - Path of Travel &amp; Discharge to Exit Path of Travel</b>	Aged Care Level 3 North Orchard
	<b>PASS</b>
	
<b>044 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Aged Care Level 2 Pin Oak Stairwell
	<b>PASS</b>
	
<b>043 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Aged Care, Level 1 North Pin Oak
	<b>PASS</b>
	
<b>042 - Path of Travel &amp; Discharge to Exit Path of Travel</b>	Aged Care, Level 1 North Pin Oak
	<b>PASS</b>
	
<b>041 - Path of Travel &amp; Discharge to Exit Discharge from Exit</b>	Aged Care, Level 1 Exits
	<b>PASS</b>

Asset	Status
	
<b>040 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Aged Care, Level 2 South Bellbird Dell Stairwell
<b>PASS</b>	
	
<b>039 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Aged Care, Level 1 South Moondani
<b>PASS</b>	
	
<b>038 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Aged Care, Level 1 South Moondani Stairwell
<b>PASS</b>	
	
<b>037 - Path of Travel &amp; Discharge to Exit Path of Travel</b>	Aged Care, Level 1 South Moondani
<b>PASS</b>	
	
<b>036 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Aged Care, Level 2 South Bellbird Dell
<b>PASS</b>	
<b>035 - Path of Travel &amp; Discharge to Exit Exit Door</b>	Aged Care, Level 2 North Bellbird Dell
<b>PASS</b>	
	
<b>034 - Path of Travel &amp; Discharge to Exit Path of Travel</b>	Aged Care, Level 2 North Bellbird Dell
<b>PASS</b>	

Asset		Status
	033 - Path of Travel & Discharge to Exit Path of Travel	Aged Care, Level 2 South Bellbird Dell
		<b>PASS</b>
	032 - Path of Travel & Discharge to Exit Discharge from Exit	Aged Care, Level 2 Exits
		<b>PASS</b>
	031 - Path of Travel & Discharge to Exit Exit Door	Aged Care, Level 2 Reception
		<b>PASS</b>
	030 - Path of Travel & Discharge to Exit Exit Door	Aged Care, Level 2 Main Entrance
		<b>PASS</b>

### Signoff

Maintenance has been carried out in accordance with current regulations.

Technician	Date/Time	Accreditations	Signature
Micra Service Technician	9th Sep 2024 12AM		
Mike Alford	9th Sep 2024 12AM		

### Company Accreditations: