

SERVICE REPORT

<p>Australian Unity - Drummond Place</p> <p>500 Drummond Street Carlton Victoria 3053</p>	<p>Report Number R-00396</p> <p>Reference DRUMOND-2400291</p> <p>Service Date: 5th June 2024</p>
--	---

Scope of Works
Path of Travel & Discharge to Exit (2012): Quarterly (20)

0 Critical Defects	A defect that renders a system inoperative.
0 Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0 Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0 Recommendations	A modification suggested to improve the system performance.
0 Informational Notes	Detailed advice or general comment.

Servicing Summary		
Service	Asset	Quantity
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	20

Maintenance

Path of Travel & Discharge to Exit (2012): Quarterly		
Asset		Status
022 - Path of Travel & Discharge to Exit Exit Door	Basement 3 Workshop	PASS

Asset		Status
021 - Path of Travel & Discharge to Exit Path of Travel	Basement 3	PASS
020 - Path of Travel & Discharge to Exit Path of Travel	Basement 2	PASS
019 - Path of Travel & Discharge to Exit Path of Travel	Basement 1	PASS
018 - Path of Travel & Discharge to Exit Path of Travel	1st Hallway	PASS
017 - Path of Travel & Discharge to Exit Path of Travel	2nd Hallway	PASS
014 - Path of Travel & Discharge to Exit Path of Travel	3rd Hallway	PASS
013 - Path of Travel & Discharge to Exit Path of Travel	3rd Hallway	PASS
012 - Path of Travel & Discharge to Exit Path of Travel	4th Hallway	PASS
011 - Path of Travel & Discharge to Exit Path of Travel	5th Hallway	PASS
010 - Path of Travel & Discharge to Exit Path of Travel	6th Hallway	PASS
009 - Path of Travel & Discharge to Exit Path of Travel	7th Hallway	PASS
008 - Path of Travel & Discharge to Exit Path of Travel	8th Hallway	PASS
007 - Path of Travel & Discharge to Exit Exit Door	Roof South Stairwell	PASS
006 - Path of Travel & Discharge to Exit Exit Door	Roof North Stairwell	PASS
003 - Path of Travel & Discharge to Exit Exit Door	Ground South West Exit	PASS

Asset		Status
004 - Path of Travel & Discharge to Exit Exit Door	Ground Floor, South	PASS
003 - Path of Travel & Discharge to Exit Discharge from Exit	Ground Floor	PASS
002 - Path of Travel & Discharge to Exit Exit Door	Ground Floor, Entrance	PASS
001 - Path of Travel & Discharge to Exit Path of Travel	Ground Floor	PASS

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Air Technician	5th Jun 2024 12AM		

Company Accreditations: