Micra Fire Pty Ltd
11/35 Dunlop Road Mulgrave VIC 3170
ABN: 43 661 051 494
03 9590 6100
service@micrafire.com.au
www.micraservice.com.au

SERVICE REPORT

Australian Unity - Geelong Grove Community Centre

50 Barwarre Road
Marshall
Victoria 3216

Report Number R-00369
Reference GEELONG-2400298
Service Date: 13th May 2024

Scope of Works

Path of Travel & Discharge to Exit (2012): Quarterly (2)

0	Critical Defects	A defect that renders a system inoperative.
0	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.

Servicing Summary

Service	Asset	Quantity
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	2

Maintenance

Path of Travel & Discharge to Exit (2012): Quarterly

Asset		Status
002 - Path of Travel & Discharge to Exit Path of Travel	Community Centre, Workshop, Cottage	PASS

Asset		Status
001 - Path of Travel & Discharge to Exit Discharge from Exit	Community Centre, Workshop, Cottage	PASS

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Fire Technician	13th May 2024 12AM		
Mike Alford	13th May 2024 12AM		

Company Accreditations: