

SERVICE REPORT

Styleknit	Report Number R-01739
Factory 10, 35 Dunlop Road	Reference
Mulgrave	Service Date:
Victoria 3170	

Scope of Works
15 - Emergency escape lighting and exit signs (2012): Annual (2)

0	Critical Defects	A defect that renders a system inoperative.
2	Non-critical Defects	A system impairment not likely to critically affect the operation of the system.
0	Non-conformances	Missing information or incorrect feature that does not affect the system operation.
0	Recommendations	A modification suggested to improve the system performance.
0	Informational Notes	Detailed advice or general comment.
2	Passed Assets	

Servicing Summary		
Service	Asset	Quantity
15 - Emergency escape lighting and exit signs (2012): Annual	15 - Emergency - Exit Signs	2

Maintenance

15 - Emergency escape lighting and exit signs (2012): Annual

AS2293.2-2019 - Emergency escape lighting and exit signs for buildings

Asset	Status
002 - Exit Sign Jumbo (Wall Mount) - Exit Styleknit ground floor	PASS
001 - Exit Sign Quick Fit (Wall Mount) - Exit Styleknit 1st floor office	PASS

Repairs

001 - Exit Sign Quick Fit (Wall Mount) - Exit Styleknit 1st floor office	PASS
---	------

RESOLVED Non-critical defect
ID: 875 [↗](#)

Added: 23rd Apr 2024 4:39PM
Last Verified: 23rd Apr 2024 4:39PM

Description:

Emergency luminaire / exit sign not operating as required

Before



After



Click photos to enlarge

Parts/Labour	Quantity
--------------	----------

002 - Exit Sign Jumbo (Wall Mount) - Exit Styleknit ground floor	PASS
---	------

RESOLVED Non-critical defect
ID: 876 [↗](#)

Added: 23rd Apr 2024 4:39PM
Last Verified: 23rd Apr 2024 4:40PM

Description:

Emergency luminaire / exit sign not operating as required

Before



After



Click photos to enlarge

Parts/Labour	Quantity
--------------	----------

Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Service Technician	None		
Mike Alford	None		

Company Accreditations: