

## SERVICE REPORT

<p><b>Australian Unity - Walmsley Aged Care</b></p> <p>500 Greeves Drive          Kilsyth          Victoria 3137</p>	<p><b>Report Number R-00156</b></p> <p><b>Reference WALMS-AC2400080</b></p> <p><b>Service Date: 20th March 2024</b></p>
--	---

<b>Scope of Works</b>	
Path of Travel & Discharge to Exit (2012): Quarterly (1)	

<b>0 Critical Defects</b>	A defect that renders a system inoperative.
<b>0 Non-critical Defects</b>	A system impairment not likely to critically affect the operation of the system.
<b>0 Non-conformances</b>	Missing information or incorrect feature that does not affect the system operation.
<b>0 Recommendations</b>	A modification suggested to improve the system performance.
<b>0 Informational Notes</b>	Detailed advice or general comment.

<b>Servicing Summary</b>		
Service	Asset	Quantity
Path of Travel & Discharge to Exit (2012): Quarterly	12 - Path of Travel & Discharge to Exit	19

## Maintenance

<b>Path of Travel &amp; Discharge to Exit (2012): Quarterly</b>		
Asset		Status
019 - Path of Travel & Discharge to Exit Exit Door	Ground Floor East Fire Stairwell	<span style="background-color: #27ae60; color: white; padding: 2px 5px; font-weight: bold;">PASS</span>

Asset		Status
018 - Path of Travel & Discharge to Exit Discharge from Exit	Ground Floor all Exits to Assembly Point	PASS
017 - Path of Travel & Discharge to Exit Path of Travel	Ground Floor	PASS
016 - Path of Travel & Discharge to Exit Path of Travel	1st Floor	PASS
015 - Path of Travel & Discharge to Exit Exit Door	1st Tulip Stairwell	PASS
014 - Path of Travel & Discharge to Exit Exit Door	1st Fern Stairwell	PASS
013 - Path of Travel & Discharge to Exit Exit Door	1st Warratah Stairwell	PASS
012 - Path of Travel & Discharge to Exit Exit Door	Ground Kitchen	PASS
011 - Path of Travel & Discharge to Exit Exit Door	Ground Delivery Entrance	PASS
010 - Path of Travel & Discharge to Exit Exit Door	Ground Hydrangea Fire Stairwell	PASS
009 - Path of Travel & Discharge to Exit Exit Door	Ground South Protea	PASS
008 - Path of Travel & Discharge to Exit Exit Door	Ground Protea Fire Stairwell	PASS
007 - Path of Travel & Discharge to Exit Exit Door	Ground North Magnolia	PASS
006 - Path of Travel & Discharge to Exit Exit Door	Ground North West Magnolia	PASS
005 - Path of Travel & Discharge to Exit Exit Door	Ground North Magnolia Fire Stair	PASS
004 - Path of Travel & Discharge to Exit Exit Door	Ground North Exit	PASS

Asset		Status
003 - Path of Travel & Discharge to Exit Exit Door	Ground Main Entrance, Airlock	PASS
002 - Path of Travel & Discharge to Exit Exit Door	Ground Main Entrance	PASS
001 - Path of Travel & Discharge to Exit		NO TEST

### Signoff

Maintenance has been carried out in accordance with Part 15 of the Victorian Building Regulations 2018.

Technician	Date/Time	Accreditations	Signature
Micra Fire Technician	20th Mar 2024 10:42AM		

### Company Accreditations: